

County Surveyor's Record, Douglas County, Oregon

2955

Dependent Resurvey, Portion of Subdivisional Lines, T. 25 S., R. 7 W.

CHAINS	
32.00	Bottom of descent, slopes N. 75° W.; asc. 60 ft. over SW. slope.
39.69	Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 2, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> T 25 S R 7 W $\frac{1}{4}$ S 2 S 1 1967 </div> from which <div style="margin-left: 40px;"> A cedar, 32 ins. diam., bears N. 73$\frac{1}{4}$° E., 147 lks. dist., mkd. $\frac{1}{4}$ S1 BT. A fir, 38 ins. diam., bears S. 17$\frac{1}{4}$° W., 226 lks. dist., mkd. $\frac{1}{4}$ S2 BT. </div> Descend 300 ft. along broken W. slope changing to NW. slope.
64.50	Spur, slopes NW.; desc. 500 ft. over steep rocky NE. slope.
74.00	Lost Creek, 12 lks. wide, course W. curving to NW.; asc. 35 ft. over rocky SW. slope.
75.00	Top of ascent, slopes W.; desc. 20 ft. along W. slope changing to NW. slope.
77.00	Creek 3 lks. wide, course W.; asc. 10 ft. over SW. slope.
77.50	Top of ascent, slopes W.; desc. 40 ft. over NW. slope.
80.00	Creek, 7 lks. wide, course N. 70° W.; asc. 30 ft. over SW. slope.
81.62	The cor. of secs. 1, 2, 35, and 36, on the N. bdy. of the tp. Land, mountainous. Soil, rocky cly with rock outcroppings. Timber, fir, cedar, hemlock, maple, chinquapin, madrone, yew, and alder; undergrowth, young timber, fern, salal, poison oak, Oregon grape, hazel, arrowwood, vine maple manzanita, ceanothus, blackberry, and salmonberry.
	From the cor. of secs. 13, 14, 23, and 24. S. 88° 07' W., bet. secs. 14 and 23. Descend 400 ft. over SW. slope of rock bluffs.
11.00	Ravine, drains S. 30° E.; asc. 300 ft. over E. slope of rock bluffs.
17.25	Top of rock bluffs, edge bears N. 30° W. and S. 30° E.; over steep E. slope, asc. 200 ft. through heavy timber and moderate undergrowth.
20.285	Point for the E 1/16 sec. cor. of secs. 14 and 23.