

# County Surveyor's Record, Douglas County, Oregon

1956

Dependent Resurvey, Portion of Subdivisional Lines, T. 25 S. R. 7 W.

CHAINS	
	<p>Set an ironpost, 28 ins. long, 2½ ins. diam., 24 ins in the ground, with brass cap mdk.</p> $\begin{array}{r} S 14 \\ E 1/16 \quad \underline{\hspace{1.5cm}} \\ S 23 \\ 1968 \end{array}$ <p>from which</p> <p>A fir, 13 ins. diam., bears N. 33° E., 114 lks. dist., mkd. E 1/16 S14 BT.</p> <p>A fir, 17 ins. diam., bears S. 79½° E., 44 lks. dist., mkd. E 1/16 S23 BT.</p> <p>Ascend 310 ft. over steep E. slope.</p>
29.00	Spur, slopes S.; desc. 225 ft. over W. slope, through scattering timber.
37.50	Dirt road, 20 lks. wide, bears N. and S. 35° W.
40.57	Point for the ¼ sec. cor. of secs. 14 and 23, at proportionate distance.; there is no remaining evidence of the original corner.
	<p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mdk.</p> $\begin{array}{r} T 25 S R 7 W \\ \frac{1}{4} \quad \underline{\hspace{1.5cm}} \\ S 14 \\ S 23 \\ 1968 \end{array}$ <p>from which</p> <p>A fir, 9 ins. diam., bears N. 30° E., 28½ lks. dist., mkd. ¼ S14 BT.</p> <p>A fir, 12 ins. diam., bears S. 33° E., 38½ lks. dist., mkd. ¼ S23 BT.</p> <p>Descend 110 ft. over W. slope.</p>
47.20	Creek, 3 lks. wide, course S. 60° W.; desc. 100 ft. over SW. slope.
57.80	Spring seepage, drains S.; asc. 15 ft. along S. slope.
59.00	Top of ascent, slopes S.; desc. 85 ft. over SW. slope.
65.70	Creek, 2 lks. wide, course S.; desc. 45 ft. over SW. slope.
69.40	Creek, 1 lk wide, course S.; asc. 20 ft. along S. slope.
78.25	Small spur, slopes S.; continue along S. slope.
80.35	Ravine, drains S.; asc. 10 ft. over SE. slope.
81.14	The cor. of secs. 14, 15, 22, and 23, perpetuated and recorded by Arthur Boyer, Deputy County Surveyor, in 1944, again perpetuated and recorded by J. W. Byron, Deputy County Surveyor, in 1959; monumented with an iron post, 1 in. diam., protruding 12 ins. above ground, firmly set, with brass cap mdk.