

County Surveyor's Record, Douglas County, Oregon

1957

Dependent Resurvey, Portion of Subdivisional Lines, T. 25 S., R. 7 W.

CHAINS

COUNTY SURVEYORS OFFICE

T 25 S R 7 W

S 15 | S 14

S 22 | S 23

1959

from which the remaining original bearing tree:

A white oak, 12 ins. diam., bears N. 55° W.;
60 lks. dist., with scribe marks S15 visible on
opened and rotted blaze. (Record, N. 55° W., 62 lks.)

and bearing trees mkd. by Boyer in 1944

A cedar, 18 ins. diam., bears S. 65° W., 34
lks. dist., with scribe marks S22 CS BT.
visible on open blaze.

An oak snag, 15 ins. diam., bears N. 21½° W.,
58 lks. dist., with illegible scribe marks
visible on rotted blaze.

and bearing trees mkd. by Byron in 1959

A cedar, 8 ins. diam., bears N. 76½° E., 45 lks.
dist., with scribe marks T25S R7W S14
CS BT visible on open double blaze.

A fir, 25 ins. diam., bears S. 58¼° E., 47
lks. dist., with a healed double blaze.

A fir, 11 ins. diam., bears N. 4 3/4° W.,
49½ lks. dist., with a healed double
blaze.

Land, mountainous.

Soil, rocky clay with rock outcroppings.

Timber, fir, cedar, madrone, maple, alder, yew, and oak;
undergrowth, young timber, fern, salal, poison oak, vine
maple, hazel, and Oregon grape.

From the ¼ sec. cor. of secs. 33 and 34, perpetuated and
recorded by Edwin Woodford, Registered Engineer No. 622
in 1949, when an original bearing tree was still existent,
monumented with a steel shaft, with gear attached, 30 ins.
long, ½ in. diam., protruding 4 ins. above the
ground, firmly set, from which bearing trees mkd. by
Woodford, in 1949:

An oak, 25 ins. diam., bears N. 1° E., 90
lks. dist., with a healed double blaze.

An oak, 19 ins. diam., bears N. 24 3/4° W.,
101 lks. dist., with a healed double blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins.
in the ground, with brass cap mkd.

T 25 S R 7 W

¼

S 33 | S 34

1968

Deposit the shaft alongside the iron post.