

County Surveyor's Record, Douglas County, Oregon

14979

Dependent Resurvey, Portion of Subdivisional Lines,
T. 30 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

and bearing trees marked by Markham

A root hole, bears S. 18° W., 24 lks. dist., with a down fir alongside, 3 ins. diam., with healed blaze.

A fir, 15 ins. diam., bears S. 24° W., 83 1/2 lks. dist., with partial scribe marks visible on pitched over blaze.

A fir snag, 3 ins. diam., bears S. 58° W., 11 lks. dist., with healed blaze.

and unrecorded bearing trees

A fir, 55 ins. diam., bears S. 11° W., 121 lks. dist., with scribe marks 30S 3W S2 SBT visible on partially healed blaze.

A fir, 17 ins. diam., bears S. 50° W., 112 lks. dist., with fragmentary scribe marks visible on partially healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 20 ins. in the ground, with brass cap mkd.

T 30 S R 3 W
S 15 | S 14
S 22 | S 23
1972

from which a new bearing tree

A fir, 49 ins. diam., bears N. 41 1/2° E., 188 1/2 lks. dist., mkd. T30S R3W S14 BT.

Reset iron rod alongside iron post.

N. 89° 38' W., bet. secs. 15 and 22, marking and blazing the true line.

Descend 40 ft. over SW. slope, through scattering timber and moderate undergrowth.

0.95	Ravine, drains N. 40° W.; continue desc. 10 ft. over NE slope.
1.75	Spur, slopes N.; continue desc. 130 ft. over NW. slope.
8.50	Dirt road, 20 lks. wide, bears N. 40° E., and S. 30° W.
9.85	Creek, 15 lks. wide, course S. 10° E.; asc. 210 ft. over SE. slope.
13.70	Gravelled road, 30 lks. wide, bears N. 35° E., and S. 35° W.
17.10	Spur, slopes S. 10° E.; desc. 35 ft. over SW. slope.
18.75	Enter heavy timber.
20.10	Creek, 2 lks. wide, course S. 10° E.; asc. 300 ft. over SE. slope.
27.95	Spur, slopes S.; desc. 270 ft. over SW. slope.