

# County Surveyor's Record, Douglas County, Oregon

**14993**

Dependent Resurvey of a Portion of the South Boundary,  
T. 21 S., R. 6 W., Willamette Meridian, Oregon

**CHAINS**

- 41.06 Creek, 5 lks. wide, course S. 25° E.; asc. 435 ft. over SE. slope.
- 51.45 Spur, slopes S. 30° E.; desc. 425 ft. over SW. slope.
- 62.45 Dirt road, 15 lks. wide, bears N. 20° W. and S. 10° W., in curve.
- 78.96 The cor. of secs. 4, 5, 32, and 33, on the S. bdy. of the Tp., perpetuated and recorded by Milo E. Godfrey, Deputy County Surveyor, in 1961, monumented with an iron pipe, 1 in. diam., firmly set, protruding 8 ins. above ground, alongside of which is the original basalt stone, 15 x 8 x 4 ins., firmly set, mkd. with 4 notches on W. edge and X on top. The iron post has a brass cap, 2 1/2 ins. diam., mkd.

COUNTY SURVEYORS OFFICE

T 21 S    R 6 W  
           S 32 | S 33  
           S 5 | S 4  
 T 22 S R 6 W  
 1961

from which the remains of the original bearing trees

A decayed fir snag, 21 ins. diam., bears N. 50° E.,  
47 lks. dist., no marks visible on decayed face.  
(Record, N. 52° E.)

A decayed cedar stump, size indeterminate, bears  
S. 40° E., 17 lks. dist., no marks visible.  
(Record, S. 50° E., 27 lks.)

and bearing trees mkd. by Godfrey

A fir, 16 ins. diam., bears N. 6 1/2° E., 34 1/2 lks.  
dist., with healed double blaze.

A fir, 20 ins. diam., bears S. 20° E., 30 lks.  
dist., with healed double blaze.

A root hole, bears S. 21 1/2° W., 33 lks. dist., with  
a down fir alongside, 16 ins. diam., no marks  
visible.

A fir, 10 ins. diam., bears N. 86 1/2 ° W., 21 lks.  
dist., with healed double blaze.

No other suitable bearing tree available within  
limits.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, cedar, alder, maple, white fir,  
and yew; undergrowth, vine maple, poison oak, fern, hazel,  
huckleberry, and arrowwood.

GENERAL DESCRIPTION

That portion of township 21 south, range 6 west that was resurveyed, is located about 5 miles northwesterly of Drain, Oregon. The area is drained by Parker Creek, and several small creeks, draining southerly to Elk Creek. Elevations range from about 650 feet above