

# County Surveyor's Record, Douglas County, Oregon

14994

Dependent Resurvey of a Portion of the South Boundary,  
T. 21 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

sea level near the corner of sections 4, 5, 32, and 33, to about 1050 feet above sea level near the 1/4 corner of sections 4 and 33.

Access is gained by way of a number of gravelled roads extending into the Parker Creek and Johney Creek drainage areas, from Oregon State Highway No. 38.

Soil in the area is a rocky clay loam. Most of the area is forested with fir, cedar, hemlock, white fir, alder, maple, and yew. The undergrowth is generally very dense and is primarily vine maple, hazel, arrowwood, huckleberry, poison oak, and fern.

No mineral deposits or mining activity was noted in the area.

An average of a considerable number of observations made, gives a value of  $19^{\circ} 30'$  E. for the mean magnetic declination. There is a range of up to  $30'$  due to local attraction.