

County Surveyor's Record, Douglas County, Oregon

15001

Dependent Resurvey, Portion of Subdivisional Lines,
T. 25 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

A madrone, 6 ins. diam., bears S. 78° E., 57 lks.
dist., with scribe marks S BT visible on partially
healed blaze.

A fir, 26 ins. diam., bears S. 30° W., 141 lks.
dist., with healed double blaze.

The corner point is located at intersection of fences,
extends N. and S.

N. 0° 15' E., beginning new measurement.

Descend 25 ft. over NW. slope.

6.50 Ravine, drains S. 40° W.; asc. 210 ft. over broken SE. slope.

20.03 Point for the N 1/16 sec. cor. of secs. 2 and 3.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins.
in the ground, with brass cap mkd.

N 1/16
S 3 | S 2
1972

from which

A fir, 12 ins. diam., bears N. 80° E., 31 lks.
dist., mkd. N 1/16 S2 BT.

A fir, 12 ins. diam., bears S. 27 1/2° W., 46 lks.
dist., mkd. N 1/16 S3 BT.

The corner point is located .020 chs. East of wire fence
extending N. and S.

Ascend 60 ft. over SE. slope.

24.40 Dirt road, 20 lks. wide, bears N. 50° W. and S. 50° E.,
also slope changes to NW.

41.37 The cor. of secs. 2, 3, 34, and 35, on the N. bdy. of the
Tp.

Land, mountainous.

Soil, rocky clay.

Timber, white oak, black oak, fir, madrone, and pine;
undergrowth, poison oak, hazel, wild strawberry, blackberry,
and fern.

From the cor. of secs. 2, 3, 10, and 11.

N. 89° 23' W., bet. secs. 3 and 10.

Ascend slightly over SE. slope, through scattering timber
and undergrowth.

2.30 Spur, slopes S. 30° E.; desc. 60 ft. over SW. slope.

3.00 Gravelled road, 20 lks. wide, bears N. 20° W. and S. 20° E.

3.80 Wire fence, bears N. 30° W. and S. 30° E.

5.00 Center line of Oregon State Highway No. 138, 40 lks.