

# County Surveyor's Record, Douglas County, Oregon

15020

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 21 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

Set an iron post, 28 ins. long 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

T 21 S	R 4 W
S 8	S 9
S 17	S 16
1972	

from which

A cedar, 9 ins. diam., bears N. 24° E., 56 lks. dist.,

A fir, 7 ins. diam., bears S. 12° E., 6 lks. dist., mkd. T21S R4W S16 BT.

A fir, 13 ins. diam., bears S. 45° W., 7 lks. dist., mkd. T21S R4W S17 BT.

A fir, 13 ins. diam., bears N. 20° W., 43 lks. dist., mkd. T21S R4W S8 BT.

From this point, the cor. of secs. 9, 10, 15, and 16, bears N. 89° 08' E., 79.13 chs. dist., perpetuated and recorded by Charles C. Bayles, Registered Engineer, No. 2306, in 1947, from original evidence no longer in existence monumented with an iron pipe 1 in. diam., firmly set, protruding 10 ins. above ground.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

T 21 S	R 4 W
S 9	S 10
S 16	S 15
1972	

from which new bearing trees

A cedar, 10 ins. diam., bears S. 12° E., 21 lks. dist., mkd. T21S R4W S15 BT.

A fir, 17 ins. diam., bears S. 36° W., 23 lks. dist., mkd. T21S R4W S16 BT.

No other trees available within limits.

Deposit the iron pipe alongside the iron post.

This control line was fully retraced, and careful search was made for evidence of intervening corners, none of which was recovered.

From this same point the 1/4 sec. cor. of secs. 8 and 9, bears N. 1° 04' E., 40.05 chs. dist., perpetuated by C. W. Springer, Deputy County Surveyor, in 1923, subsequently perpetuated by Vernon R. Trace, Deputy County Surveyor, in 1966, monumented with an iron pipe, 2 ins. diam. firmly set, protruding 14 ins. above ground, from which the remains of the original bearing trees:

A sawed fir stump, 36 ins. diam., bears N. 43° W., 34 lks. dist., with scribe marks BT visible on opened blaze.