

# County Surveyor's Record, Douglas County, Oregon

15011

15022

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 25 S., R. 8 W., Willamette Meridian, Oregon

CHAINS	and bearing trees mkd. by Tracy
	<p>A hemlock, 12 ins. diam., bears N. 14° E., 34 lks. dist., with scribe marks T25S R8W S21 CS BT. visible on open blaze.</p> <p>A hemlock, 14 ins. diam., bears S. 61° E., 60 1/2 lks. dist., with scribe marks T25S R8W S28 CS BT. visible on open blaze.</p> <p>Land, mountainous. Soil, rocky clay loam. Timber, fir, hemlock, cedar, oak, maple, yew, alder, and chinquapin' undergrowth, salal, hazel, vine maple, fern, Oregon grape, blackberry, and huckleberry.</p>
	N. 3° 08' E., on the W. bdy. of sec. 21.
	Ascend 270 ft. over SW. slope, through heavy timber and dense undergrowth.
10.80	Spur, slopes S. 65° W.; desc. 75 ft. over NW. slope.
18.50	Creek, 25 lks. wide, course S. 15° W.; asc. 240 ft. over S. slope.
25.95	Top of ascent, slopes S.; desc. 5 ft. over NE. slope.
26.60	Creek, 5 lks. wide, course S. 65° E.; asc. 230 ft. over SE. slope.
31.65	Rocky spur, slopes S. 30° E.; asc. 200 ft. over SE. slope.
35.80	Dirt road, 20 lks. wide, bears N. 65° E. and S. 65° W.
36.80	Point for the 1/4 sec. cor of sec. 20 only; hereinafter described.
	Ascend 20 ft. over S. slope.
37.75	Spur, slopes S. 75° E.; desc. 55 ft. over NE. slope.
39.82	Point for the 1/4 sec. cor. of sec. 21 only, at proportionate distance; there is no remaining evidence of the original corner. No permanent monument established.
41.25	Creek, 3 lks. wide, course SE.; asc. 140 ft. over SW. slope.
49.75	Ridge, bears E. and W.; desc. 175 ft. over N. slope.
53.45	Rock bluff, faces NW.; desc. 590 ft. over broken NW. slope.
69.35	Creek, 7 lks. wide, course N. 65° E.; asc. 130 ft. over SE. slope.
74.70	Spur, slopes E.; desc. 95 ft. over NE. slope.
76.48	True point for the closing cor. of secs. 17 and 20, on the W. bdy. of sec. 21, hereinafter described.
	Descend 50 ft. over broken NE. slope.