

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,
T. 25 S., R. 8 W., Willamette Meridian, Oregon

CHAINS
77.25

Creek, 10 lks. wide, course S. 65° E.; asc. 135 ft.
over SE. slope.

79.64

The cor. of secs. 16 and 21, determined at record bearing
and distance from the remains of the original bearing
trees:

A root hole, bears N. 68° 30' E., 27 lks. dist.,
with a down fir alongside, 40 ins. diam., with
scribe marks T25S R8W visible on partially
healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins.
in the ground, with brass cap mkd.

T 25 S R 8 W
S 16 S 16
S 21 S 21
1972

from which new bearing trees

A hemlock, 13 ins. diam., bears N. 38° E., 48 lks.
dist., mkd. T25S R8W S16 BT.

A hemlock, 18 ins. diam., bears S. 28° E., 41 1/2 lks.
dist., mkd. T25S R8W S21 BT.

Land, Mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, cedar, maple, oak, madrone, alder,
and chinquapin; undergrowth, salal, hazel, vine maple,
Oregon grape, huckleberry, blackberry, arrowwood, and
fern.

From the cor. of secs. 29, 30, 31, and 32, determined
at record distance from the remaining original bearing
trees:

A cedar, 20 ins. diam., bears S. 20° 15' W., 50
lks. dist., with fragmentary scribe marks visible
on decayed blaze and a galvanized nail, with "W"
embossed on the head, driven into base.

A cedar, 30 ins. diam., bears N. 28° W., 18 lks.
dist., with fragmentary scribe marks visible on
decayed blaze and a galvanized nail, with "W"
embossed on the head, driven into base. (Record,
N. 32° 10' W.)

and bearing trees of which I have no record

A cedar, 14 ins. diam., bears N. 87° E., 102 lks.
dist., with a galvanized nail, with "W" embossed
on the head, driven into base.

A fir, 33 ins. diam., bears S. 28° E., 275 lks.
dist., with a galvanized nail, with "W" embossed
on the head, driven into base.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins.
in the ground, with brass cap mkd.