

County Surveyor's Record, Douglas County, Oregon

15057

Dependent Resurvey of a Portion of the East Boundary,
T. 22 S., R. 5 W., Willamette Meridian, Oregon

CHAINS

A sawed fir stump, 40 ins. diam., bears
N. 53° W., 30 lks. dist., with scribe marks
4S visible on opened blaze.

and bearing trees mkd. by Godfrey

A fir, 22 ins. diam., bears S. 32° E., 56 lks.
dist., with healed blaze.

A fir, 16 ins. diam., bears N. 45° W., 77 lks.
dist., with healed blaze.

N. 0° 24' E., bet. secs. 25 and 30.

Ascend 15 ft. over SE. slope, through heavy timber and
moderate undergrowth.

2.00 Spur, slopes SE.; desc. 250 ft. over NE. slope.

19.90 Point for the N 1/16 sec. cor. of secs. 25 and 30.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins.
in the ground, with brass cap mkd.

N 1/16
S 25 | S 30
1973

from which

A fir, 10 ins. diam., bears N. 60° E., 4 lks.
dist., mkd. N 1/16 S30 BT.

A fir, 20 ins. diam., bears S. 56 1/2° W., 33 1/2 lks.
dist., mkd. N. 1/16 S25 BT.

Descend 160 ft. over NE. slope.

30.80 Slope changes to N.; desc. 80 ft. over N. slope.

35.30 Creek, 1 lk. wide, course N. 80° E.; asc. 65 ft. over
SE. slope.

39.80 The cor. of secs. 19, 24, 25 and 30 perpetuated by
James W. Byron, Deputy County Surveyor, in 1959, from
original evidence no longer in existence, subsequently
perpetuated by Milo E. Godfrey, Deputy County Surveyor,
in 1963, monumented with an iron post, 1 1/2 ins. diam.,
firmly set, protruding 10 ins. above ground, with brass
cap mkd.

COUNTY SURVEYORS OFFICE
T 22 S
R5W $\frac{S 24 | S 19}{S 25 | S 30}$ R4W
1959

from which bearing trees mkd. by Byron

A fir, 10 ins. diam., bears N. 20° E., 75 lks.
dist., with healed blaze.

A fir, 9 ins. diam., bears S. 30° E., 39 lks.
dist., with healed blaze.

A fir, 7 ins. diam., bears N. 25° W., 47 lks.
dist., with healed blaze.