

# County Surveyor's Record, Douglas County, Oregon

1007

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 22 S., R. 5 W., Willamette Meridian, Oregon

**CHAINS**

A sawed fir stump, 38 ins. diam., bears S. 70°W.,  
41 1/2 lks. dist., with scribe marks BT visible on  
opened blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins.  
in the ground, with brass cap mkd. FDOK PER PEEL  
2-23-88 M105-69

1/4  
S 22 | S 23  
T 22 S R 5 W  
1973

from which a new bearing tree

A fir, 6 ins. diam., bears S. 79° E., 58 lks.  
dist., mkd. 1/4 S23 BT.

Deposit wooden post alongside iron post.

From this corner, a point established by Weyerhaeuser  
Timber Co., in 1960, bears S. 53 1/2° W., 0.033 chs. dist.,  
monumented with a galvanized nail, with "W" embossed on  
head, driven into a root.

N. 0° 15' E., beginning new measurement.

Descend 75 ft. over NW. slope.

11.05 Elk Creek, 60 lks. wide, course S. 40° W.; asc. 410 ft.  
over SE. slope.

15.20 Gravelled road, 25 lks. wide, bears N. 80° E. and  
S. 80° W.

41.44 The cor. of secs. 14, 15, 22 and 23, perpetuated by  
James W. Byron, Deputy County Surveyor, in 1958, monu-  
mented with an iron rebar, 1 in. diam., firmly set,  
protruding 6 ins. above ground, from which the remains  
of the original bearing tree:

A black oak, 46 ins. diam., bears N. 9° E., 21 lks.  
dist., with scribe marks 2 S visible on opened  
blaze.

and bearing trees mkd. by Byron

A fir, 25 ins. diam., bears N. 70° E., 37 lks.  
dist., with healed blaze.

A fir, 12 ins. diam., bears S. 38° E., 25 lks.  
dist., with healed blaze.

A fir, 15 ins. diam., bears S. 20° W., 46 1/2 lks.  
dist., with healed blaze.

A fir, 17 ins. diam., bears N. 7° W., 35 1/2 lks.  
dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins.  
in the ground, with brass cap mkd.