

# County Surveyor's Record, Douglas County, Oregon

15068

~~80000~~

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 22 S., R. 5 W., Willamette Meridian, Oregon.

**CHAINS**

FD. OK 9/94 BY BAKER  
M 119-39

T 22 S R 5 W  
S 15 | S 14  
S 22 | S 23  
1973

Deposit iron rebar alongside iron post.

Land, mountainous.  
Soil, rocky clay loam.  
Timber, fir, hemlock, cedar, madrone, maple and chinquapin; undergrowth, vine maple, hazel, salal, fern and blackberry.

From the cor. of secs. 13, 14, 23 and 24.

S. 89° 54' W., bet. secs. 14 and 23.

Descend 100 ft. over SW. slope, through heavy timber and moderate undergrowth.

- 6.15 Elk Creek, 70 lks. wide, course SW.; asc. 235 ft. over broken SE. slope.
- 8.35 Leave timber and undergrowth, edge bears N. and S.; enter open field.
- 16.75 Paved road, 30 lks. wide, bears N. 40° E., and S. 40° W.
- 22.95 Dirt road, 10 lks. wide, bears N. 30° E. and S. 30° W.
- 31.70 Same dirt road, 10 lks. wide, bears N. 25° W. and S. 25° E.
- 37.40 Dirt road, 10 lks. wide, bears N. 10° E. and S. 10° W.
- 39.77 Point for the 1/4 sec. cor. of secs. 14 and 23, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

FD. OK 9/94 BY BAKER  
M 119-39

1/4 S 14  
S 23  
T 22 S R 5 W  
1973

FD OK PER PEEL  
2/23/88 M 105-69

No suitable bearing trees available within limits.

Ascend 75 ft. over broken SE. slope.

- 50.80 Spur, slopes S.; desc. 205 ft. over SW slope.
- 51.50 Leave open field, edge bears N. and S.; enter heavy timber and moderate undergrowth.
- 59.60 Wire fence, bears N. 10° E. and S. 10° W.
- 60.45 Ravine, drains S. 5° W.; asc. 265 ft. over SE. slope.
- 79.54 The cor. of secs. 14, 15, 22 and 23.

Land, mountainous.  
Soil, rocky clay loam.  
Timber, fir, hemlock, cedar, white oak, black oak and