

# County Surveyor's Record, Douglas County, Oregon

15075

Dependent Resurvey of a Portion of the Subdivisional  
Lines, T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

T28S R8W  

$$\begin{array}{r|l} S\ 21 & S\ 22 \\ \hline S\ 28 & S\ 27 \\ \hline 1973 \end{array}$$

from which new bearing trees

A fir, 9 ins. diam., bears N. 30° E., 100 lks.  
dist., mkd. T28S R8W S22 BT.

A cedar, 20 ins. diam., bears S. 48 1/2° W., 71 lks.  
dist., mkd. T28S R8W S28 BT.

Land, mountainous.

Soil, clay loam.

Timber, fir, hemlock, cedar, alder, maple and madrone;  
undergrowth, vine maple, hazel, salal, fern and poison oak.

From the cor. of secs. 22, 23, 26 and 27, perpetuated  
by James W. Byron, Deputy County Surveyor, in 1957,  
monumented with an iron post, 1 1/2 ins. diam., firmly  
set, protruding 10 ins. above ground, with brass cap  
mkd.

COUNTY SURVEYOR'S OFFICE  
T28S R8W  

$$\begin{array}{r|l} 22 & 23 \\ \hline 27 & 26 \\ \hline 1957 \end{array}$$

from which the remains of the original bearing trees

A root hole, bears N. 78° E., 29 lks. dist.

A root hole, bears S. 72° E., 49 lks. dist.

A root hole, bears S. 5° W., 62 lks. dist.

and bearing trees marked by Byron

A cedar, 20 ins. diam., bears N. 18° E., 26 lks.  
dist., with healed blaze.

A maple, 19 ins. diam., bears S. 36° E., 90 lks.  
dist., with healed blaze.

A fir, 18 ins. diam., bears S. 55° W., 55 lks.  
dist., with healed blaze.

A fir, 18 ins. diam., bears N. 89 1/2° W., 69 lks.  
dist., with healed blaze.

S 89° 26' W., bet. secs. 22 and 27.

Ascend 135 ft. over E. slope, through moderate timber  
and dense undergrowth.

8.30 Ridge, bears S. 15° W., and N. 15° E.; desc. 120 ft.  
over W. slope.

15.65 Ravine, drains S. 20° W.; asc. 30 ft. over SE slope.

19.05 Spur, slopes S.; desc. 10 ft. over SW. slope.