

County Surveyor's Record, Douglas County, Oregon

15080

Dependent Resurvey of a Portion of the Subdivisional
Lines, T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

S. 89° 19' W., bet. secs. 10 and 15.

Ascend 40 ft. over SE. slope, through heavy timber and moderate undergrowth.

2.95 Spur, slopes S.; des. 180 ft. over W. slope.

5.25 Wire fence, bears N. 80° E., and S. 80° W.

8.90 Dirt road, 20 lks. wide, bears N. 15° W., and S. 15° E.

10.05 Creek, 6 lks. wide, course S. 15° E.; asc. 315 ft. over NE. slope.

19.94 Point for the E 1/16 sec. cor. of secs. 10 and 15.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16 $\frac{S\ 10}{S\ 15}$
1969

from which

A fir, 80 ins. diam., bears N. 7° W., 81 lks. dist., mkd. E 1/16 S10 BT.

A fir, 8 ins. diam., bears S. 28° W., 41 lks. dist., mkd. E 1/16 S15 BT.

Corner falls 10 lks. S. of wire fence extending E. and W.

Continue ascending 40 ft. over NE. slope.

22.60 Spur, slopes N.; desc. 150 ft. over NW. slope.

25.70 Slope changes to SW.

31.90 Ravine, drains S.; asc. 65 ft. over E. slope.

37.05 Spur, slopes S. 25° W.; desc. 70 ft. over W. slope.

39.88 Point for the 1/4 sec. cor. of secs. 10 and 15, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 28 S R 8 W
1/4 $\frac{S\ 10}{S\ 15}$
1969

FD OK PER BRUBAKER
M 109-53 11/89

from which

A fir, 7 ins. diam., bears N. 17 1/2° W., 48 lks. dist., mkd. 1/4 S10 BT.

A chinquapin, 7 ins. diam., bears S. 33° W., 16 lks. dist., mkd. 1/4 S15 BT.

Corner falls 6 lks. S. of wire fence extending E. and W.

Continue descending 80 ft. over W. slope.