

County Surveyor's Record, Douglas County, Oregon

15083

Dependent Resurvey of a Portion of the Subdivisional
Lines, T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

38.75

Point for the 1/4 sec. cor. of secs. 3 and 10, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 12 ins. in the ground, and in a mound of stone, 4 ft. base, to top, with brass cap mkd.

*3/91 FD 6K
M111-70*

T 28 S R 8 W
1/4 $\frac{S 3}{S 10}$
1969

from which

A fir, 12 ins. diam., bears N. 33° W., 15 1/2 lks. dist., mkd. 1/4 S3 BT.

A fir, 43 ins. diam., bears S. 24 1/2° W., 24 1/2 lks. dist., mkd. 1/4 S10 BT.

Continue ascending 200 ft. over SE. slope.

43.85

Spur, slopes S. 15° E.; desc. 25 ft. over SW. slope.

46.15

Ravine, drains S.; asc. 225 ft. over SE. slope.

52.90

Ridge, bears NE. and SW.; desc. 330 ft. over W. slope.

77.50

The cor. of secs. 3, 4, 9 and 10.

Land, mountainous.

Soil, rocky clay with scattered rock outcroppings.
Timber, fir, hemlock, cedar, madrone, myrtle, oak, alder, and chinquapin; undergrowth, vine maple, Oregon grape, salal, fern, poison oak, rhododendron, blackberry, huckleberry, salmonberry and elderberry.

From the cor. of secs. 21, 22, 27 and 28.

S. 88° 52' W., bet. secs. 21 and 28.

Descend 95 ft. over W. slope, through scattering timber and dense undergrowth.

2.10

Creek, 3 lks. wide, course N. 25° W.; asc. 45 ft. over NE. slope.

6.30

Spur, slopes N.; desc. 105 ft. along broken N. slope.

23.70

Dirt road, 15 lks. wide, bears N. 35° E., and S. 35° W.

32.70

Ravine, drains N. 45° E.; asc. 80 ft. over broken NE. slope.

37.80

Same dirt road, 15 lks. wide, bears N. and S.

40.32

Point for the 1/4 sec. cor. of secs. 21 and 28, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.