

County Surveyor's Record, Douglas County, Oregon

15085

Dependent Resurvey of a Portion of the Subdivisional
Lines, T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

Soil, rocky clay loam.
Timber, fir, hemlock, cedar, maple, alder, madrone and chinquapin; undergrowth, vine maple, hazel, fern, salal, and poison oak.

From the cor. of secs. 9, 10, 15 and 16.

N. 89° 36' W., bet. secs. 9 and 16.

Ascend 60 ft. over S. slope, through moderate timber and undergrowth.

13.50 Slope changes to SE.

18.45 Spur, slopes S. 20° E.; desc. 200 ft. over SW. slope.

29.85 Slope changes to W.

30.85 Burnt Mountain Access Road, asphaltic surfaced, 30 lks. wide, bears N. and S., curving from E. to NW.

33.20 Dirt road, 10 lks. wide, bears N. and S.

35.50 Creek, 10 lks. wide, course S. 20° W., asc. 140 ft. over SE. slope.

40.07 The 1/4 sec. cor. of secs. 9 and 16, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1957, monumented with an iron pipe, 1 1/2 ins. diam., firmly set, protruding 8 ins. above ground, with brass cap mkd.

COUNTY SURVEYOR'S OFFICE
T 28 S R 8 W
1/4 sec $\frac{9}{16}$
1957

from which the original bearing trees

A fir, 48 ins. diam., bears S. 25° E., 14 lks. dist., with scribe marks 1/4 BT visible on bark. (Record, S. 32° E., 10 lks. dist.)

A hemlock, 26 ins. diam., bears N. 44 1/2° W., 27 lks. dist., with healed blaze. (Record, fir, N. 41 1/2° W.)

and bearing trees marked by Byron

A yew, 13 ins. diam., bears N. 25° W., 45 1/2 lks. dist., with scribe markd 1/4 S9 BT visible on partially healed blaze.

A white fir, 25 ins. diam., bears S. 50° E., 82 lks. dist., with scribe marks 1/4 S16 BT visible on partially healed blaze.

Land, mountainous.
Soil, rocky clay with scattered rock outcroppings.
Timber, fir, hemlock, cedar, madrone, oak, alder, myrtle and chinquapin; undergrowth, vine maple, Oregon grape, salal, fern, poison oak, rhododendron, blackberry, huckleberry, salmonberry and elderberry.