

# County Surveyor's Record, Douglas County, Oregon

15087

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

A cedar, 35 ins. diam., bears N. 61° E., 56 lks. dist., mkd. 1/4 S20 BT.

A hemlock, 6 ins. diam., bears S. 67° W., 53 lks. dist., mkd. 1/4 S19 BT.

Ascend 25 ft. over SW. slope.

42.60 Ridge, bears N. 50° W.; desc. 220 ft. over NW. slope.

58.25 Ravine, drains N. 80° E.; asc. 280 ft. over S. slope.

78.90 Spur ridge, bears N. 60° E., and S. 60° W.; desc. 110 ft. over N. slope.

81.38 Point for the cor. of secs. 17, 18, 19 and 20, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 28 S R 8 W  
 S 18 | S 17  
 S 19 | S 20  
 1972

*FD. OK 7/10/85  
 R. Gausman C.S. 4, 1988  
 C.S. 63/22*

from which

A fir, 20 ins. diam., bears N. 82° E., 72 lks. dist., mkd. T28S R8W S17 BT.

A hemlock, 22 ins. diam., bears S. 5° E., 37 lks. dist., mkd T28S R8W S20 BT.

A cedar, 20 ins. diam., bears S. 84° W., 53 lks. dist., mkd T28S R8W S19 BT.

A hemlock, 11 ins. diam., bears N. 42° W., 37 lks. dist., mkd T28S R8W S18 BT.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, cedar, alder, maple and madrone; undergrowth, vine maple, hazel, salal, poison oak and fern.

From the cor. of secs. 16, 17, 20 and 21, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1957, monumented with an iron pipe 2 ins. diam., firmly set, protruding 8 ins. above ground, with brass cap mkd.

COUNTY SURVEYOR'S OFFICE

T 28 S R 8 W  
 S 17 | S 16  
 S 20 | S 21  
 1957

from which the remains of the original bearing trees

A fir, 45 ins. diam., bears S. 68 1/2° W., 46 lks. dist., with healed blaze.

A fir stump, 50 ins. diam., bears N. 40° W., 41 lks. dist., no marks visible.