

# County Surveyor's Record, Douglas County, Oregon

15094

Dependent Resurvey of a Portion of the Subdivisional  
Lines, T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

and remains of bearing trees marked by Byron

A fir stump, 60 ins. diam., bears N. 66° E., 136  
lks. dist., with scribe mks. T28S R8W S7 BT  
visible on bark blaze.

A fir stump, 72 ins. diam., bears N. 57° W., 127  
lks. dist., with scribe mks. T28S R9W S12 BT  
visible on bark blaze.

No other suitable trees within limits.

Corner falls on N. edge of Coos Bay Wagon Road, 40 lks.  
wide, bears N. 30° W., and S. 30° E.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, cedar, yew, maple and madrone;  
undergrowth, salal, huckleberry, rhododendron, fern  
and ocean spray.

From the cor. of secs. 7, 8, 17 and 18.

N. 1° 21' W., bet. secs. 7 and 8.

Ascend 140 ft. over S. slope, through heavy timber and  
light undergrowth.

- 3.20 Burnt Ridge Road, dirt, 20 lks. wide, bears E. and W.
- 6.75 Burnt Ridge Road, dirt, 20 lks. wide, bears N. 80° E.,  
and S. 80° W.
- 7.75 Spur, slopes S. 80° W.; desc. 270 ft. over NW. slope.
- 26.80 Creek, 2 lks. wide, course N. 30° W.; asc. 10 ft. over  
SE. slope.
- 30.25 Spur, slopes N. 20° W.; desc. 45 ft. over N. slope.
- 35.00 Creek, 4 lks. wide, course N. 30° W.; asc. 10 ft. over  
SE. slope.
- 36.40 Top of ascent, slopes W.; desc. 50 ft. over NW. slope.
- 39.53 The 1/4 sec. cor. of secs. 7 and 8, perpetuated and  
recorded by James W. Byron, Deputy County Surveyor, in  
1957. Byron found the root hole of the original corner  
tree, a down hemlock, 20 ins. diam., alongside, with no  
marks visible, the corner is monumented with an iron  
pipe, 2 ins. diam., firmly set, protruding 2 ins. above  
the ground, in the center of the root hole, with brass  
cap mkd.

COUNTY SURVEYOR'S  
T 28 S R 8 W  
1/4 S 7 | S 8  
1957  
OFFICE

from which the remains of the original bearing tree

A root hole, bears S. 68° E., 31 lks. dist.

and the remains of bearing trees marked by Byron