

# County Surveyor's Record, Douglas County, Oregon

15119

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 25 S., R. 2 W., Willamette Meridian, Oregon.

**CHAINS**

- 20.15 Gravelled road, 15 lks. wide, in curve, bears N. 40° W. and East
- 23.70 Creek, 10 lks. wide, course N. 80° W.; asc. 30 ft. along W. slope.
- 40.01 The cor. of secs. 22, 23, 26, and 27, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1958, monumented with an iron post, 1 1/2 ins. diam., firmly set, protruding 12 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 25 S  
S 22 | S 23  
S 27 | S 26  
R 2 W  
1958

from which the remains of the original bearing trees

A sugar pine, 63 ins. diam., bears N. 37° E., 63 1/2 lks. dist., with healed blaze. (Record, 59 lks.)

A fir snag, 33 ins. diam., bears S. 25° E., 35 lks. dist., with healed blaze. (Record, 32 lks.)

A root hole, bears S. 31° W., 51 lks. dist., with a down fir, alongside, 36 ins. diam., no marks visible.

A fir, 45 ins. diam., bears N. 44° W., 55 lks. dist., with healed blaze.

and a bearing tree mkd. by Byron

A hemlock, 8 ins. diam., bears S. 80 1/2° W., 32 lks. dist., with healed double blaze.

\*\*\* →

Land, mountainous.  
Soil, rocky clay loam.  
Timber, fir, pine, cedar, hemlock, madrone, chinquapin, maple, and yew; undergrowth, salal, Oregon grape, hazel, vine maple, poison oak, young timber, rhododendron, and fern.

From the cor. of secs. 23, 24, 25, and 26.

S. 89° 35' W., bet. secs. 23 and 26.

Descend 85 ft. over over W. slope, through heavy timber and light undergrowth.

2.50 Creek, 2 lks. wide, course NW.; asc. 15 ft. over NE. slope.

5.25 Top of ascent, slopes N.; desc. 40 ft. over NW. slope.

8.10 Bottom of descent, slopes N.; asc. 10 ft. over NE. slope.

10.50 Spur, slopes N. 10° W.; desc. 370 ft. over NW. slope.

\*\*\* and a new bearing tree

A hemlock, 7 ins. diam., bears S. 53° E., 16 lks. dist., mkd. T25S R2W S26 BT.