

# County Surveyor's Record, Douglas County, Oregon

15132

Subdivision of Section 32, T. 25 S., R. 2 W.,  
Willamette Meridian, Oregon

**CHAINS**

- 6.05 Spur, slopes S. 82° W.; desc. 125 ft. over NW. slope.
- 11.60 Ravine, drains. N. 70° W.; desc. 20 ft. over W. slope.
- 15.35 Spur, slopes N. 34° W.; desc. 75 ft. over NE. slope.
- 18.31 Point for the center S 1/16 sec. cor. of sec. 32.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 23 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} C \\ S\ 1/16\ S\ 32 \\ C \\ 1975 \end{array}$$

from which

A fir, 8 ins. diam., bears N. 88° E., 20 lks. dist., mkd.. CS 1/16 S32 BT.

A fir, 10 ins. diam., bears S. 62° W., 13 1/2 lks. dist., mkd. CS 1/16 S32 BT.

Descend 125 ft. over NE. slope.

- 26.55 Spur, slopes N. 70° E.; desc. 70 ft. over NW. slope.
- 27.40 Ravine, drains. N. 54° E.; asc. 20 ft. over SE. slope.
- 30.20 Spur, slopes N. 36° E.; desc. 200 ft. over NW. slope.

40.01 The center 1/4 sec. cor. of sec. 32, established and recorded by Vernon W. Hosford, RLS No. 253, in 1960, monumented with an iron pipe, 1 1/2 ins. diam., firmly set, protruding 5 ins. above ground, from which the remains of the bearing trees mkd. by Hosford:

A root hole, bears S. 74° E., 33 lks. dist., with a down hemlock alongside, 20 ins. diam., with healed blaze.

A hemlock snag, 17 ins. diam., bears N. 58° W., 9 lks. dist., with scribe marks C 1/4 S32 visible on open blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 25 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} C\ 1/4 \\ S\ 32 \\ 1975 \end{array}$$

from which new bearing trees

A cedar, 27 ins. diam., bears S. 42° E., 61 1/2 lks. dist., mkd. C 1/4 S32 BT.

A cedar, 14 ins. diam., bears N. 65° W., 18 1/2 lks. dist., mkd. C 1/4 S32 BT.

Reset iron pipe alongside iron post.

N. 0° 09' W., beginning new measurement.