

County Surveyor's Record, Douglas County, Oregon

15147

Dependent Resurvey, Portion of Subdivisional Lines,
T. 30 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

1/4
S 26 | S 25
T 30 S | R 7 W
1971

from which new bearing trees

A pine, 16 ins. diam., bears S. 25° E., 63 lks.
dist., mkd. 1/4 S25 BT.

A pine, 18 ins. diam., bears S. 47 1/4° W., 94 lks.
dist., mkd. 1/4 S26 BT.

N. 3° 38' E., beginning new measurement.

Ascend 125 ft. over broken SE. slope.

- 5.60 Spur, slopes S. 75° E.; desc. 40 ft. over NE. slope.
 - 8.20 Creek, 2 lks. wide, course S. 55° W.; asc. 125 ft. over SE. slope.
 - 12.00 Spur, slopes S. 60° E.; desc. 20 ft. over broken NE. slope.
 - 15.50 Ravine, drains. S. 65° E.; asc. 255 ft. over SE. slope.
 - 27.80 Spur, slopes E.; desc. 265 ft. over broken NE. slope.
 - 38.20 Creek, 2 lks. wide, course N. 75° E.; asc. 55 ft. over SE. slope.
 - 39.05 The cor. of secs. 23, 24, 25, and 26, perpetuated and recorded by John H. Markam, Jr., Registered Logging Engineer No. 2880, in 1951, monumented with an iron pipe, 1 in. diam., firmly set, projecting 4 ins. above ground, from which the remains of the original bearing trees;
 - A fir, 26 ins. diam., bears N. 12 1/2° E., 54 lks. dist., with healed blaze. (Record, N. 5° E.,)
 - A fir snag, 35 ins. diam., bears S. 65° E., 53 lks. dist., with healed balze. (Record, S. 68° E.,)
 - A root hole, bears S. 30° W., 9 lks. dist., with a down fir alongside, 33 ins. diam., with healed blaze.
 - A cedar, 35 ins. diam., bears N. 1° W., 42 lks. dist., with healed blaze.
- and a bearing tree mkd. by Markham
- A root hole, bears S. 45° E., 20 lks. dist., with a down fir, alongside, 11 ins. diam., with healed blaze.
- At the corner point
- Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 30 S R 7 W
S 23 | S 24
S 26 | S 25
1971