

County Surveyor's Record, Douglas County, Oregon

15165

Dependent Resurvey, Portion of Subdivisional Lines,
T. 26 S., R. 7 W., Willamette Meridian, Oregon.

CHAINS

From the cor. of secs. 26, 27, ~~33~~³⁵, and 34, determined at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, with brass cap mkd.

*FD. ok 4-91
D. BENTZ MLD
1991-54*

T 26 S R 7 W
S 27 S 26
S 34 S 35
1974

from which

An alder, 12 ins. diam., bears N. 64° E., 230 lks. dist., mkd. T26S R7W S26 BT.

A fir, 23 ins. diam., bears S. 22° E., 310 lks. dist., mkd. T26S R7W S35 BT.

A fir, 21 ins. diam., bears S. 27 3/4° W., 206 lks. dist., mkd. T26S R7W S34 BT.

A power pole, No. 149, bears N. 47 1/2° W., 41 lks. dist.

The corner is located on the NW. cor. of Elgarose Road, paved, 40 lks. wide, bears E. and S.

From this point, the cor. of secs. 25, 26, 35, and 36, bears N. 89° 58' E., 80.12 chs. dist., perpetuated by person(s) unknown, further perpetuated and recorded by the Douglas County Surveyor, in 1959, monumented with an iron post, 2 ins. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd.

T 26 S
26 25
35 36
7 W

*FD. ok 11/81
K. D. Stewart
M 89-51*

from which the remains of an original bearing tree

A root hole, bears S. 83° E., 62 lks. dist., with a down oak snag alongside, 20 ins. diam., with scribe marks S36 visible on open blaze.

and bearing trees of which I have no record

A fir, 17 ins. diam., bears N. 72° E., 7 lks. dist., with healed blaze.

A madrone, 10 ins. diam., bears S. 23° E., 19 1/2 lks. dist., with healed blaze.

A fir, 16 ins. diam., bears S. 49° W., 49 lks. dist., with healed blaze.

and a bearing tree mkd. in 1959

A fir, 15 ins. diam., bears N. 75° W., 59 lks. dist., with healed blaze.

Add marks BLM 1974 to brass cap.

This control line was fully retraced and careful search was made for evidence of intervening corners, none of which was recovered.