

# County Surveyor's Record, Douglas County, Oregon

**15169**

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 26 S., R. 7 W., Willamette Meridian, Oregon

CHAINS	T 26 S R 7 W 1/4 S 33   S 34 1974
	from which  An oak, 10 ins. diam., bears N. 83° W., 75 lks. dist., mkd. 1/4 S33 BT.  No other suitable trees available within limits.  Ascend 50 ft. over SE. slope.
42.35	Gravelled road, 10 lks. wide, bears E. and W.
50.15	Woven wire fence, extends E. and W.
50.20	Top of ascent, slopes S. 75° E.; desc. 25 ft. over NE. slope.
59.97	Point for the N 1/16 sec. cor. of secs. 33 and 34.  Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.  <div style="text-align: center;">                         N 1/16                          S 33   S 34                          1974                     </div> from which  A madrone, 13 ins. diam., bears S. 73 1/3° E., 22 lks. dist., mkd. N 1/16 S34 BT.  A fir, 6 ins. diam., bears N. 75 1/2° W., 127 lks. dist., mkd. N 1/16 S33 BT.  Descend 5 ft. over NE. slope.
60.75	Ravine, drains NE.; asc. 35 ft. over SE. slope.
66.80	Top of ascent, slopes E.; desc. 5 ft. over NE. slope.
67.80	Ravine, drains E.; continue descent 15 ft. over NE. slope.
70.50	Creek, 1 lk. wide, course N. 85° E.; asc. 30 ft. over SE. slope.
73.75	Creek, 1 lk. wide, course N. 80° E.; desc. 10 ft. over NE. slope.
78.85	Enter beaver pond, 1.50 chs. wide, 2.50 chs. long, edge bears N. 30° W. and S. 30° E.
79.96	Point for the cor. of secs. 27, 28, 33, and 34, at proportionate distance; there is no remaining evidence of the original corner. This point is located in a beaver pond, where it is impracticable to establish a permanent monument.  Land, rolling hills. Soil, rocky loam. Timber, fir, oak, hemlock, cedar, madrone, wild cherry, and alder; undergrowth, wild rose, manzanita, willow, arrowwood, poison oak, and fern.