

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the East Boundary,
T. 26 S., R. 8 W., Willamette Meridian, Oregon.

15202

CHAINS
20.295

Point for the N 1/16 sec. cor. of secs. 7 and 12.

Set an iron post, 28 ins. long 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

N 1/16
S 12 | S 7
1971

from which

A fir, 32 ins. diam., bears N. 2° E., 37 lks. dist., mkd. N 1/16 S7 BT.

A chinquapin, 6 ins. diam., bears N. 53° W., 16 lks. dist., mkd. N 1/16 S12 BT.

Ascend 70 ft. over SW. slope.

21.85 Spur, slopes S. 80° W.; desc. 35 ft. over NW. slope.

30.10 Creek, 5 lks. wide, course S. 45° W.; asc. 375 ft. over SW. slope.

37.55 Spur, slopes N. 75° W.; desc. 30 ft. over NW. slope.

40.59 Point for the cor. of secs. 1, 6, 7, and 12, determined by the method of irregular boundaries; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

T 26 S
R 8 W R 7 W
S 1 | S 6
S 12 | S 7
1971

from which

A madrone, 4 ins. diam., bears S. 83° E., 26 lks. dist., mkd. X BT.

A fir, 15 ins. diam., bears S. 5° E., 29 lks. dist., mkd. T26S R7W S7 BT.

A fir, 23 ins. diam., bears S. 39° W., 74 lks. dist., mkd. T26S R8W S12 BT.

No other suitable trees available within limits.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, madrone, cedar, maple, tan oak, and chinquapin; undergrowth, salal, rhododendron, hazel, fern, poison oak, and vine maple.

N. 0° 05' W., bet. secs. 1 and 6.

Descend 130 ft. over NW. slope. through scattering timber and dense undergrowth.

12.45 Creek, 3 lks. wide, course S. 75° W.; asc. 85 ft. over SW. slope.

24.00 Spur, slopes W.; desc. 20 ft. over nearly level ground.