

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines,  
T. 26 S., R. 8 W., Willamette Meridian, Oregon

15210

CHAINS

with an iron pipe, 2 ins. diam., firmly set, protruding 6 ins. above ground, from which the remains of the original bearing trees:

A cedar, 25 ins. diam., bears S. 72° W., 108 lks. dist., with healed blaze.

A broken fir stump, bears N. 14° W., 31 lks. dist., with a down and decayed fir alongside, 36 ins. diam., with healed blaze.

and bearing trees mkd. by the County Surveyor, in 1968

A fir, 15 ins. diam., bears N. 68° E., 14 lks. dist., with healed blaze.

A fir, 13 ins. diam., bears S. 40° E., 27 lks. dist., with healed blaze.

A fir, 12 ins. diam., bears N. 49° W., 26 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

T 26 S R 8 W  
S 23 | S 24  
S 26 | S 25  
1971

Deposit the iron pipe alongside the iron post.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, maple, chinquapin, and madrone; undergrowth, salal, fern, rhododendron, hazel, vine maple, and poison oak.

N. 0° 05' W., bet. secs. 23, and 24.

Ascend 100 ft. along W. slope, through heavy timber and light undergrowth.

16.50 Spur, slopes NW.; desc. 40 ft. over NW. slope.

20.11 Point for the S 1/16 sec. cor. of secs. 23 and 24.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

S 1/16  
S 23 | S 24  
1971

from which

A fir, 13 ins. diam., bears N. 51° E., 48 lks. dist., mkd. S 1/16 S24 BT.

A fir, 13 ins. diam bears S. 28 1/2° W., 27 lks. dist., mkd. S 1/16 S23 BT.

Descend 200 ft. over NW. slope.