

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of the Subdivisional Lines
T. 26 S., R. 8 W., Willamette Meridian, Oregon.

15212

CHAINS

T 26 S
S 14 | S 13
S 23 | S 24
R 8 W
1971

from which the remains of the original bearing trees

A root hole, bears N. 29° E., 32 lks. dist., with a down hemlock alongside, 12 ins. diam., no marks visible.

A fir, 30 ins. diam., bears S. 55° W., 28 lks. dist., with healed blaze.

A fir, 28 ins. diam., bears N. 39° W., 29 lks. dist., with fragmentary scribe marks visible on opened blaze.

and bearing trees mkd. by Tracy, in 1968

A fir, 22 ins. diam., bears N. 88° E., 43 lks. dist., with healed blaze.

A hemlock, 10 ins. diam., bears S. 24 1/2 E., 14 lks. dist., with scribe marks T26S R8W S24 CS BT.

A hemlock, 6 ins. diam., bears S. 30° W., 26 lks. dist. with scribe marks S23 CS BT visible on open blaze.

A fir, 25 ins. diam., bears N. 55° W., 8 lks. dist., with healed blaze.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, maple, chinquapin, and madrone; undergrowth, salal, fern, rhododendron, hazel, vine maple, and poison oak.

From the cor. of secs. 13, 18, 19, and 24, on the E. bdy. of the Tp.

N. 89° 49' W., bet. secs. 13 and 24.

Ascend 270 ft. over SE. slope, across logged area, through scattering timber and dense undergrowth.

7.30 Spur, slopes S. 20° E., desc. 25 ft. over SW. slope.

8.80 Ravine, drains S. 35° E.; asc. 925 ft. over SE. slope.

40.29 Point for the 1/4 sec. cor. of secs. 13 and 24, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

1/4 S 13
 S 24
T 26 S R 8 W
1971

from which