

County Surveyor's Record, Douglas County, Oregon

15213

Dependent Resurvey, Portion of the Subdivisional Lines,
T. 26 S., R. 8 W., Willamette Meridian, Oregon.

CHAINS	
	<p>A fir, 6 ins. diam., bears N. 38 1/2° W., 28 lks. dist., mkd. 1/4 S13 BT.</p> <p>A fir, 4 ins. diam., bears S. 10° W., 24 lks. dist., mkd. 1/4 S24 BT.</p> <p>Ascend 220 ft. over SE. slope.</p>
56.30	Enter heavy timber, edge bears N. and S.
60.435	Point for the W 1/16 sec. cor. of secs. 13 and 24.
	<p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;"> $\begin{array}{c} W\ 1/16\ \frac{S\ 13}{S\ 24} \\ 1971 \end{array}$ </p> <p>from which</p> <p>A fir, 27 ins. diam., bears N. 38° W., 93 lks. dist., mkd. W 1/16 S13 BT.</p> <p>A fir, 23 ins. diam., bears S. 32 3/4° W., 126 lks. dist., mkd. W 1/16 S24 BT.</p> <p>Ascend 40 ft. over SE. slope.</p>
62.00	Spur, slopes S. 30° W.; desc. 265 ft. over SW. slope.
64.80	Dirt road, 25 lks. wide, bears N. 30° E., and S. 30° W.
80.58	The cor. of secs. 13, 14, 23, and 24.
	<p>Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, cedar, maple, chinquapin, and madrone; undergrowth, salal, fern, rhododendron, hazel, vine maple, and poison oak.</p>
	<p>N. 0° 09' E., bet. secs. 13 and 24.</p> <p>Ascend 55 ft. along W. slope, through heavy reproduction and dense undergrowth.</p>
7.35	Spur, slopes S. 80° W.; desc. 100 ft. along W. slope.
18.90	Creek, 4 lks. wide, course W.; asc. 60 ft. over SW. slope.
19.95	Dirt road, 15 lks. wide, bears S. 70° W., and N. 70° E.
30.25	Spur, slopes S. 40° W.; desc. 20 ft. over NW. slope.
32.90	Creek, 4 lks. wide, course S. 40° W.; asc. 90 ft. over SE. slope.
40.43	The 1/4 sec. cor. of secs. 13 and 14, perpetuated and recorded by Vernon R. Tracy, Deputy County Surveyor, in 1968, monumented with an iron post, 1 1/2 ins. diam., firmly set, protruding 8 ins. above ground, with brass cap mkd.
	<p>T 26 S 1/4 S 14 S 13 R 8 W 1968</p>