

County Surveyor's Record, Douglas County, Oregon

15219

Dependent Resurvey, Portion of the Subdivisional Lines,
T. 26 S., R. 8 W., Willamette Meridian, Oregon.

CHAINS

and bearing trees mkd. by Tracy

A hemlock, 13 ins. diam., bears S. 46° E., 46 lks. dist., with scribe marks T26S R8W S12 CC CS BT visible on open blaze.

A sawed hemlock stump, 11 ins. diam., bears S. 4° W., 56 lks. dist., with scribe marks T26S R8W S11 CC CS BT visible on open blaze.

and a new bearing tree

A hemlock, 9 ins. diam., bears S. 36 1/2° W., 86 lks. dist., mkd. T26S R8W S11 CC BT.

Descend 10 ft. over NW. slope.

From this point the cor. of secs. 1 and 2 only, bears N. 89° 23' E., 2.26 chs. dist.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, maple, chinquapin, and madrone; undergrowth, salal, fern rhododendron, hazel, vine maple, and poison oak.

From the cor. of secs. 1, 6, 7, and 12, on the E. bdy. of the Tp.

N. 89° 29' W., bet. secs. 1 and 12.

Descend 355 ft. over NW. slope.

19.38

Point for the E 1/16 sec. cor. of secs. 1 and 12.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16 $\frac{S 1}{S 12}$
1971

from which

A fir, 16 ins. diam., bears N. 49° E., 12 lks. dist., mkd. E 1/16 S1 BT.

A fir, 9 ins. diam., bears S. 85° W., 40 lks. dist., mkd. E 1/16 S12 BT.

Descend 110 ft. over NW. slope.

21.10

Hubbard Creek Road, paved, 40 lks. wide, bears N. 20° E., and S. 20° W.

25.50

Hubbard Creek, 60 lks. wide, course N. 40° E.; asc. 465 ft. over NE. slope.

38.76

Point for the 1/4 sec. cor. of secs. 1 and 12, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

1/4 $\frac{S 1}{S 12}$
T 26 S R 8 W
1971