

# County Surveyor's Record, Douglas County, Oregon

15229

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 30 S., R. 8 W., Willamette Meridian, Oregon.

## CHAINS

Soil, rocky clay loam.  
Timber, fir, hemlock, cedar, pine, madrone, oak, white fir, and chinquapin; undergrowth, salal, hazel, rhododendron, huckleberry, poison oak, fern, and vines.

### GENERAL DESCRIPTION

That portion of township 30 south, range 8 west, that was resurveyed, lies about 12 miles northwesterly of Riddle, Oregon. The area on the south boundary of the township that was resurveyed is drained by Live Oak Creek, Manzanita Creek, and several smaller creeks, draining southerly to Union Creek. The line between sections 19 and 20 is drained in a westerly direction by Boulder Creek and its tributaries. Elevations range from about 1250 feet above sea level near the S 1/16 section corner of sections 19 and 20, to about 2300 feet above sea level near the 1/4 section corner of sections 4 and 33.

Access to the south boundary is gained by way of Union Creek Access Road. Access to the line between sections 19 and 20 is gained by way of Boulder Creek Road,

Soil in the area is a rocky clay loam. Most of the area is forested with fir, cedar, pine, white fir, madrone, oak, maple, chinquapin, and hemlock; undergrowth consists of live oak, huckleberry, manzanita, salal, Oregon grape, hazel, poison oak, rhododendron, fern, and vines.

No mineral deposits or mining activity was noted in the area.

An average of a considerable number of observations made gives a value of 19° 15' E., for the mean magnetic declination. There is a range of up to 45' due to local attraction.