

County Surveyor's Record, Douglas County, Oregon

15235

Dependent Resurvey, Portion of Subdivisional Lines,
T. 24 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

A fir, 35 ins. diam., bears N. 88°W., 111 lks. dist., with healed blaze. This tree was rescribed by Byron, in 1958, and has a healed blaze.

and bearing trees mkd. by Byron

A fir, 12 ins. diam., bears N. 74° E., 24 1/2 lks. dist. with healed double blaze.

A black oak, 32 ins. diam., bears S. 23° E., 68 lks. dist., with healed double blaze.

A fir, 15 ins. diam., bears South, 20 lks. dist., with healed double blaze.

Land, mountainous.

Soil, rocky clay loam.

Timber, cedar, fir, oak, hemlock, madrone, maple, and chinquapin; undergrowth, vine maple, hazel, huckleberry, blackberry, fern, poison oak, rhododendron, manzanita, arrowwood, and salal.

N. 0° 11' E., bet. secs. 13 and 14.

Ascend 55 ft. over SE. slope, through light to moderate timber and undergrowth.

7.55 Ravine, drains S. 45° W.; continue ascent 270 ft. over SE. slope.

22.35 Spur, slopes E.; desc. 135 ft. over NE. slope.

40.07 Point for the 1/4 sec. cor. of secs. 13 and 14, at proportionate distance, there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins in the ground, with brass cap mkd.

T 24 S R 6 W
1/4
S 14 | S 13
1973

from which

A fir, 16 ins. diam., bears East, 18 lks. dist., mkd. 1/4 S13 BT.

A madrone, 5 ins. diam., bears N. 64 1/2° W., 24 lks, dist., mkd. 1/4 S14 BT.

Descend 30 ft. over NE. slope.

50.25 Ravine, drains E.; asc. 65 ft. over S. slope.

56.90 Ridge, bears E. and W.; desc. 50 ft. over NW. slope.

60.105 Point for the N 1/16 sec. cor. of secs. 13 and 14.

Set an iron post, 28 ins. long 2 1/2" diam., 22 ins. in the ground, with brass cap mkd.

N 1/16
S 14 | S 13
1973