

County Surveyor's Record, Douglas County, Oregon

15287

Dependent Resurvey of a Portion of the South Boundary,
T. 24 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

Timber, fir, hemlock, cedar, yew, madrone, alder, maple, and chinquapin; undergrowth, vine maple, salal, fern, hazel, and poison oak.

Dependent Resurvey of a portion of the Subdivisional Lines, T. 24 S., R. 7 W.
Willamette Meridian, Oregon

(Restoring the survey by Dennis Hathorn,
Deputy Surveyor, in 1858, and the survey by
Williams R. Whipple, Deputy Surveyor, in 1893-94)

From the 1/4 sec. cor. of secs. 13 and 24, perpetuated by James W. Byron, Deputy County Surveyor, in 1959, monumented with an iron post, 1 1/2 ins. diam., firmly set, protruding 10 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

1/4 S 13
 S 24
T 24 S R 7 W
1959

*Coe. for. ok 9/5/86
D.S.H.D. - CS 63/9*

from which the remains of the original bearing trees

A fir stump, 42 ins. diam., bears S. 40° W., 10 lks. dist., no marks visible on burned blaze.

and a bearing tree mkd. by the Deputy County Surveyor, in 1932

A fir stump, 66 ins. diam., bears N. 19° E., 73 1/2 lks. dist., no marks visible on burned blaze.

and a bearing tree mkd. by Byron

A fir, 16 ins. diam., bears N. 49 1/2° E., 111 1/2 lks. dist., with healed blaze.

and a new bearing tree

A fir, 7 ind. diam., bears S. 67 1/2° W., 46 1/2 lks. dist., mkd. 1/4 S24 BT.

N. 89° 36' W., bet. secs. 13 and 24, marking and blazing the true line.

Descend 400 ft. over NW. slope, through scattering timber and dense undergrowth.

19.30 State Highway No. 225, 40 lks. wide, in curve, bears' N. 50° E. and S. 60° W.

22.40 Point for the original meander cor., on right bank of Umpqua River, at proportionate distance; there is no remaining evidence of the original corner. This point is not monumented.

23.00 Right bank of Umpqua River, course N. 50° E.; thence across river.

29.23 Point for the original meander cor., on right bank of Umpqua River, at proportionate distance; there is no remaining evidence of the original corner. This point falls on eroding right bank of Umpqua River, course S. 75° E., where it is impracticable to establish a permanent monument.