

# County Surveyor's Record, Douglas County, Oregon

15291

Dependent Resurvey, Portion of Subdivisional Lines  
T. 24 S., R. 7 W., Willamette Meridian, Oregon

CHAINS	
	<p>A fir, 37 ins. diam., bears S. 71° W., 30 lks. dist., with fragmentary scribe marks visible on weathered bark blaze.</p> <p>and bearing trees mkd. by Tracy</p> <p>A fir, 25 ins. diam., bears N. 47° E., 65 1/2 lks. dist., with healed blaze.</p> <p>A fir, 10 ins. diam., bears S. 58° E., 43 lks. dist., with healed blaze.</p> <p>A fir, 13 ins. diam., bears S. 44° W., 88 lks. dist., with healed blaze.</p> <p>A fir, 13 ins. diam., bears N. 36° W., 12 lks. dist., with healed blaze.</p> <p>Land, mountainous. Soil, rocky clay loam. Timber, fir, hemlock, cedar, yew, alder, maple, madrone, and chinquapin; undergrowth, vine maple, salal, fern, hazel, salmonberry, and poison oak.</p>
	<p>From the cor. of secs. 13 and 14 only, on the N. bdy. of sec. 23.</p> <p>N. 89° 40' W., along the S. bdy. of sec. 14.</p> <p>Descend 10 ft. over NW. slope, through heavy timber and dense undergrowth.</p>
0.40	Ravine, drains N. 30° E.; asc. 95 ft. over NE. slope.
5.50	Top of ascent, slopes N. 30° E.; desc. 90 ft. over broken NW. slope.
10.80	Creek, 2 lks. wide, course N. 10° W.; asc. 505 ft. over broken SE. slope.
38.73	<p>Point for the 1/4 sec. cor. of sec. 23 only, at mid-point on the N. bdy. of sec. 23.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <p>1/4 S 23 T 24 S R 7 W 1973</p> </div> <p>from which</p> <p>A fir, 46 ins. diam., bears S. 7° E., 31 1/2 lks. dist., mkd. 1/4 S23 BT.</p> <p>A fir, 7 ins. diam., bears S. 67° W., 95 1/2 lks. dist., mkd. 1/4 S23 BT.</p> <p>Ascend 20 ft. over SE. slope.</p>
40.00	Spur, slopes N. 35° E.; desc. 5 ft. over NW. slope.
40.16	Point for the 1/4 sec. cor. of sec. 14 only, at proportionate distance; there is no remaining evidence of the original corner.