

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, 15296
T. 24 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

A fir, 10 ins. diam., bears N. 37° E., 192 1/2 lks. dist., mkd. T24S R7W S34 CC BT.

A fir, 8 ins. diam., bears N. 43 1/2° W., 126 1/2 lks. dist., mkd. T24S R7W S33 CC BT.

From this point, the original closing cor. of secs. 33 and 34, bears S. 0° 12' E., 0.075 chs. dist., perpetuated and recorded by Bruce Shaner, Registered Engineer No. 4906, in 1972, monumented with an iron post, 1 1/2 ins. diam., firmly set, protruding 10 ins. above ground, with brass cap mkd.

T 24 S R 7 W W.M.
S 33 | S 34
C C
1972

from which the remains of the original bearing trees

A sawed fir stump, 32 ins. diam., bears N. 61° E., 64 lks. dist., with healed blaze.

A twin fir snag, 17 ins. diam., bears N. 20° W., 37 lks. dist., with healed blaze.

Add marks AM 1973 to brass cap.

From this same point, the cor. of secs. 3 and 4 only, T. 25 S., R. 7 W., bears S. 89° 32' W., 3.10 chs. dist., hereinbefore described.

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, cedar, he. lock, alder, madrone, maple, chinquapin, and yew; undergrowth, vine maple, salal, fern, hazel, ocean spray, and poison oak.

From the cor. of secs. 27, 28, 33, and 34.

N. 89° 46' W., bet. secs. 28 and 33.

Descend 310 ft. over broken NW. slope, along timber edge and through dense undergrowth.

10.25 Ravine, drains N.; asc. 60 ft. over NE. slope.

12.30 Spur, slopes N.; desc. 260 ft. over broken NW. slope.

25.50 Creek, 1 lk. wide, course N. 20° W.; asc. 205 ft. over NE. slope.

30.40 Spur, slopes N. 20° W.; desc. 140 ft. over W. slope.

39.86 Point for the 1/4 sec. cor. of secs. 28 and 33, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. i the ground, with brass cap mkd.

1/4 S 28
S 33
T 24 S R 7 W
1973

*FDOK
M. Smalley
9/96 M124-27*