

# County Surveyor's Record, Douglas County, Oregon

15317

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 32 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

- 54.20 Ravine, drains W.; asc. 90 ft. over broken SW. slope.
  - 64.50 Spur, slopes N. 70° W.; desc. 85 ft. over NW. slope.
  - 67.65 Ravine, drains N. 60° W.; asc. 25 ft. over SW. slope.
  - 70.60 Spur, slopes N. 60° W.; desc. 205 ft. over NW. slope.
  - 80.26 Point for the cor. of secs. 13, 14, 23, and 24, at proportionate distance; there is no remaining evidence of the original corner.
- Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 32 S R 7 W  
S 14 | S 13  
S 23 | S 24  
1976

from which

- A fir, 20 ins. diam. bears N. 33° E., 73 lks. dist., mkd. T32S R7W S13 BT.
- A fir, 17 ins. diam., bears S. 60 1/2° E., 28 lks. dist., mkd. T32S R7W S24 BT.
- A fir, 8 ins. diam., bears S. 10° W., 58 lks. dist., mkd. T32S R7W S23 BT.
- A fir, 18 ins. diam., bears N. 29° W., 135 lks. dist., mkd. T32S R7W S14 BT.

Land, mountainous.  
Soil, rocky cly loam.  
Timber, fir, pine, chinquapin, madrone, oak, and dogwood; undergrowth, arrowwood, hazel, poson oak, fern, and salal.

- From the cor. of secs. 13, 18, 19, 24, on the E. bdy. of the Tp.
  - S. 86° 52' W., bet. secs. 13 and 24.
  - Ascend 310 ft. over SE. slope, through light timber and dense undergrowth.
  - 12.35 Creek, 1 lk. wide, course S. 40° E.; asc. 80 ft. over SE. slope.
  - 17.10 Ridge, bears N. 10° W. and S. 10° E.; desc. 55 ft. over SW. slope.
  - 19.28 Point for the E 1/16 sec. cor. of secs. 13 and 24.
- Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

E 1/16    S 13  
          S 24  
1976

from which