

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,
T. 32 S., R. 4 W., Willamette Meridian, Oregon

15341

CHAINS									
	<p>A fir, 37 ins. diam., bears S. 71 1/2° E., 207 1/2 lks. dist., mkd. E 1/16 S7 BT.</p> <p>Descend 10 ft. over gradual W. slope, across open field.</p>								
28.70	Wire fence, bears N. 20° E., and S. 20° W.								
28.90	Driveway, 15 lks. wide, bears N. 20° E., and S. 20° W.								
32.15	Cow creek, 70 lks. wide, course S. 20° W.; asc. 15 ft. over gradual SE. slope, across open field.								
33.00	Dirt road, 15 lks. wide, bears N. and S. 20° W., on curve.								
39.95	<p>The 1/4 sec. cor. of secs. 6 and 7, perpetuated and recorded by G. G. Stewart, Deputy County Surveyor, in 1922, from original 1871 corner evidence which is no longer in existence, monumented with an iron pipe, 1 1/4 ins. diam., protruding 4 ins. above the ground, firmly set, from which bearing trees mkd. by Stewart:</p> <p style="padding-left: 40px;">A cedar, 36 ins. diam., bears N. 7 1/2° W., 271 lks. dist., with healed double blaze.</p> <p style="padding-left: 40px;">A cedar, 26 ins. diam., bears S. 51° W., 14 1/2 lks. dist., with healed double blaze. (Rescribed by Byron in 1957).</p> <p>and a bearing tree mkd. by J. W. Byron, Deputy County Surveyor, in 1957</p> <p style="padding-left: 40px;">A ponderosa pine, 17 ins. diam., bears N. 22 1/2° E., 33 lks. dist., with healed double blaze.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground directly over the iron pipe, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p>T 32 S R 4 W</p> <table style="margin: auto; border-collapse: collapse;"> <tr> <td style="padding: 0 10px;">1</td> <td style="border-left: 1px solid black; padding: 0 10px;">S 6</td> <td style="padding: 0 10px;">/</td> <td style="border-left: 1px solid black; padding: 0 10px;">1871</td> </tr> <tr> <td style="padding: 0 10px;">4</td> <td></td> <td></td> <td></td> </tr> </table> </div> <p>From this point, the NE. cor. of a wood frame garage, bears N. 59° W., 0.18 chs. dist., dimensions 10 x 15 ft., long side bears S. 15° E.</p> <hr style="width: 30%; margin: 10px auto;"/> <p>S. 87° 18' W., beginning new measurement.</p> <p>Ascend 80 ft. over SE. slope.</p>	1	S 6	/	1871	4			
1	S 6	/	1871						
4									
3.90	Asphaltic surfaced road, 30 lks. wide, bears NE. and SW.; also leave open field, edge bears the same; enter medium timber and dense undergrowth.								
4.30	Driveway, 15 lks. wide, bears N. 20° E., and S. 20° W.								
6.10	Same driveway, bears N. 25° E., and S. 25° W.								
6.95	Same driveway, bears N. 20° E., and S. 20° W.								
10.05	Creek, 2 lks. wide, course SE.; asc. 190 ft. over NE. slope.								

FD A/BF
WM. RUTHERFORD
C.S. 50/215