

# County Surveyor's Record, Douglas County, Oregon

15371

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 28 S., R. 4 W., Willamette Meridian, Oregon

CHAINS	
	<p>Soil, rocky clay. Timber, fir, cedar, maple, hemlock, and madrone; undergrowth, hazel, salal, arrowwood, poison oak, Oregon grape, fern, and ceanothus.</p>
	<p>From the cor. of secs. 7, 8, 17, and 18. N. 0° 06' W., bet. secs. 7 and 8. Descend 300 ft. over NW. slope, through scattering timber and light undergrowth.</p>
3.55	Dirt road, 15 lks. wide, bears N. 50° E. and S. 60° W.
19.78	<p>Point for the S 1/16 sec. cor. of secs. 7 and 8. Set an iron post, 28 ins. long, 2 1/2 ins. diam., 20 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">S 1/16 S 7   S 8 1974</p> <p>from which</p> <p style="margin-left: 40px;">A fir, 6 ins. diam., bears N. 79° E., 185 lks. dist., mkd. S 1/16 S8 BT.</p> <p style="margin-left: 40px;">A cedar, 16 ins. diam., bears S. 38° W., 76 1/2 lks. dist., mkd. S 1/16 S7 BT.</p> <p>Descend 25 ft. over NW. slope.</p>
23.80	Creek, 1 lk. wide, course N. 40° W.; desc. 130 ft. over broken NW. slope.
34.45	Bottom of descent, slopes W.; asc. 25 ft. over SW. slope.
39.56	<p>Point for the 1/4 sec. cor. of secs. 7 and 8, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 28 S R 4 W 1/4 S 7   S 8 1974</p> <p>from which</p> <p style="margin-left: 40px;">A fir, 18 ins. diam., bears S. 46° E., 60 lks. dist., mkd. 1/4 S8 BT.</p> <p style="margin-left: 40px;">A fir, 15 ins. diam., bears S. 19° W., 39 lks. dist., mkd. 1/4 S7 BT.</p> <p>Corner is located on spur, slopes N. 85° W. Descend 155 ft. over NW. slope</p>
46.50	Bottom of descent, slopes S. 80° W.; asc. 30 ft. over SW. slope.
48.05	Spur, slopes N. 65° W.; desc. 300 ft. along broken E. slope.

FD 7/9  
G. BAUGHMAN  
M113-49