

County Surveyor's Record, Douglas County, Oregon

15387

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

(Rehabilitating a corner established by
William Thiel, in 1891, and rehabilitated
by Thomas A. Tillman and Joseph S. Gawron, in 1953)

The 1/4 sec. cor. of secs. 14 and 23, monumented with the remains of the original corner tree, a burned cedar stump, size indeterminate, no marks visible, from which the remains of the original bearing trees:

A cedar stump, 20 ins. diam., bears
S. 65° E., 9 lks. dist., no marks visible.

A fir stump, 30 ins. diam., bears
N. 44° W., 25 lks. dist., no marks visible.

and the remains of a bearing tree marked in 1953

A fir stump, 72 ins. diam., bears
N. 74° W., 25 lks. dist., mkd. 1/4 S14 BT
visible on open blaze. (Record, 20 lks.)

and a new bearing tree

A fir stump, 38 ins. diam., bears
S. 42 1/2° E., 30 lks. dist., mkd. 1/4 S23 BT.

A local reference monument, bears
N. 52° W., 7 lks. dist., monumented with an
iron pipe, 2 1/2 ins. diam., firmly set,
projecting 24 ins. above ground.

Set a 6 ft. steel fence post alongside the
iron post.

(Rehabilitating corners reestablished by
Thomas A. Tillman and Joseph S. Gawron, in 1953)

The 1/4 sec. cor. of secs. 27 and 34, monumented with an
iron post, 1 in. diam., firmly set, projecting 8 ins.
above the ground, with brass cap mkd.

1/4 S 27
S 34
1953

from which the remaining bearing tree marked in 1953

A fir, 52 ins. diam., bears S. 59° W.,
110 lks. dist., with fragmentary scribe
marks visible on partially healed blaze.

and a new bearing tree

An alder, 6 ins. diam., bears N. 18° E.,
21 lks. dist., mkd. 1/4 S27 BT.

Set a 6 ft. steel fence post alongside the iron
post.

The 1/4 sec. cor. of secs. 27 and 28, monumented with an
iron post, 1 in. diam., firmly set, projecting 10 ins.
above the ground, with brass cap mkd.

1/4
S 28 | S 27
1953

Fl. by
LES Roberts
2/28/83
M 93-64

Fl. by LES ROBERTS
2/14/83
M 90-53