

County Surveyor's Record, Douglas County, Oregon

15393

Dependent Resurvey, Portion of Subdivisional Lines,
T. 26 S., R. 3 W., Willamette Meridian, Oregon

CHAINS
59.895

Point for the N 1/16 sec. cor. of secs. 25 and 26.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

N 1/16
S 26 | S 25
1972

from which

A fir, 12 ins. diam., bears N. 71° E., 20 lks. dist., mkd. N 1/16 S25 BT.

A fir, 15 ins. diam., bears S. 73° W., 56 lks. dist., mkd. N 1/16 S26 BT.

Corner is located on spur, slopes S. 50° W.

Descend 110 ft. over NW. slope.

73.30

Creek, 2 lks. wide, course N. 30° W.; desc. 20 ft. over NW. slope.

79.86

Point for the cor. of secs. 23, 24, 25, and 26, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

T 26 S R 3 W
S 23 | S 24
S 26 | S 25
1972

from which

A fir, 50 ins. diam., bears N. 31° E., 13 lks. dist., mkd. T26S R3W S24 BT.

A hemlock, 14 ins. diam., bears S. 47° E., 22 lks. dist., mkd. T26S R3W S25 BT.

A hemlock, 13 ins. diam., bears S. 11° W., 48 lks. dist., mkd. T26S R3W S26 BT.

A hemlock, 6 ins. diam., bears N. 40° W., 25 lks. dist., mkd. T26S R3W S23 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, chinquapin, maple, alder, yew, madrone, and dogwood; undergrowth, vine maple, hazel, fern, poison oak, salal, Oregon grape, and arrow-wood.

From the 1/4 sec. cor. of secs. 24 and 25, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1957, monumented with an iron post, 2 ins. diam., firmly set, protruding 10 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 26 S R 3 W
1/4 S 24
S 25
1957