

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,
T 26 S., R 3 W., Willamette Meridian, Oregon

15397

CHAINS

from which

A cedar, 27 ins. diam., bears N. 53° E., 86 lks. dist., mkd. 1/4 S26 BT.

A cedar, 18 ins. diam., bears S. 83° E., 31 lks. dist., mkd. 1/4 S35 BT.

Descend 5 ft. over nearly level ground.

40.37 Gravelled road, 20 lks. wide, bears N. 25° E. and S. 25° W.

41.95 Ravine, drains S. 40° E.; asc. 50 ft. over NE. slope.

47.75 Ridge, bears N. 40° E. and S. 40° W.; desc. 330 ft. over NW. slope.

60.42 Point for the W 1/16 sec. cor. of secs. 26 and 35.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.

W 1/16 $\frac{S\ 26}{S\ 35}$
1972

from which

A fir, 12 ins. diam., bears N. 47° E., 29 lks. dist., mkd. W 1/16 S26 BT.

A fir, 18 ins. diam., bears S. 46° E., 8 lks. dist., mkd. W 1/16 S35 BT.

Descend 400 ft. over NW. slope.

72.65 Rattlesnake Creek, 10 lks. wide, course S. 15° W.; asc. 185 ft. over SE. slope.

80.56 The cor. of secs. 26, 27, 34, and 35.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, madrone, maple, alder, chinquapin, and dogwood; undergrowth, vine maple, hazel, fern, salal, Oregon grape, and arrowwood.

N. 0° 11' W., bet secs. 26 and 27.

Ascend 290 ft. over SE. slope, through heavy timber and light undergrowth.

20.06 Point for the S 1/16 sec. cor. of secs. 26 and 27.

Set and iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

S 1/16
S 27 | S 26
1972

from which

A cedar, 23 ins. diam., bears S. 87° E., 48 lks. dist., mkd. S 1/16 S26 BT.

FD 10K 4/86
 R. GEISLER
 C.S.
 (23 "CEDAR"
 NOW STUMP)