

County Surveyor's Record, Douglas County, Oregon

15399

Dependent Resurvey, Portion of Subdivisional Lines.
T. 26 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
	<p>Timber, fir, cedar, hemlock, alder, maple, madrone, and chinzuapin; undergrowth, vine maple, fern, hazel, salal, Oregon grape, and arrowwood.</p>
	<p>From the cor. of secs. 23, 24, 25, and 26.</p> <p>N. 89° 51' W., bet secs. 23 and 26.</p> <p>Descend 85 ft. over W. slope.</p>
4.43	<p>Creek, 1 lk. wide, course N. 50° W.; desc. 315 ft. over NW. slope.</p>
20.145	<p>Point for the E 1/16 sec. cor. of secs 23 and 26.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">E 1/16 $\frac{S\ 23}{S\ 26}$ 1972</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 8 ins. diam., bears N. 62° E., 48 lks. dist., mkd. E 1/16 S23 BT.</p> <p style="padding-left: 40px;">A fir, 7 ins. diam., bears S. 24° W., 38 lks. dist., mkd. E 1/16 S26 BT.</p> <p>Descend 15 ft. over NW slope.</p>
20.89	<p>Creek, 3 lks. wide, course S. 5° W.; asc. 35 ft. over SE slope.</p>
25.36	<p>Spur, slopes S. 10° W.; desc. 165 ft. over W. slope.</p>
40.29	<p>Point for the 1/4 sec. cor. of secs. 23 and 26, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 40 ins. in the ground, with the top 12 ins. below surface of ground, with brass cap mkd.</p> <p style="text-align: center;">T 26 S R 3 W 1/4 $\frac{S\ 23}{S\ 26}$ 1972</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 6 ins. diam., bears N. 26° E., 60 lks. dist., mkd. 1/4 S23 BT.</p> <p style="padding-left: 40px;">A fir, 20 ins. diam., bears S. 22° W., 101 lks. dist., mkd. 1/4 S26 BT.</p> <p>Descend 15 ft. over SW. slope.</p>
40.37	<p>Gravelled road, 20 lks. wide, bears N. 40° W. and S. 40° E.</p>
44.09	<p>Creek, 2 lks. wide, course S. 70° W.; asc. 260 ft. over SE. slope.</p>