

# County Surveyor's Record, Douglas County, Oregon

15400

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 26 S. R. 3 W., Willamette Meridiana, Oregon

CHAINS	
58.75	Dirt road, 10 lks. wide, bears N. 40° E and S. 40° W.
80.58	The Cor. of secs. 22, 23, 26, and 27.  Land, mountainous. Soil, rocky clay. Timber, fir, cedar, hemlock, madrone, alder, maple, yew, and dogwood; undergrowth, vine maple, hazel, fern, salal, Oregon grape, and arrowwood.
	N. 1° 24' E., bet. secs. 22 and 23.  Ascend 140 ft. over S. slope, through scattering timber and dense undergrowth.
16.20	Dirt road, 20 lks. wide, bears S. 55° W. and N. 55° E
17.50	Spur, slopes N. 50° E.; desc. 240 ft. over N. slope.
40.14	Point for the 1/4 sec. cor. of secs. 22 and 23, at proportionate distance; there is no remaining evidence of the original corner.  Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.
	T 26 S R 3 W 1/4 s 22   S 23 1972
	from which  A cedar, 26 ins. diam., bears S. 38° E., 43 lks. dist., mkd. 1/4 S23 BT.  A fir, 6 ins. diam., bears S. 89° W., 55 lks. dist., mkd. 1/4 S22 BT.
	Descend 505 ft. over N. slope.
51.73	Dirt road, 20 lks. wide, bears N. 50° E. and S. 50° W.
74.60	Creek, 2 lks. wide, course N. 35° W.; asc. 35 ft. over NW slope.
80.28	The cor. of secs. 14, 15, 22, and 23, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1960, monumented with an iron post, 1 in. diam., firmly set, protruding 18 ins. above ground, with brass cap mkd.
	T 26 S R 3 W S 15   S 14 S 22   S 23 1960
	from which the remains of the original bearing tree  A root hole, bears S. 87° E., 50 lks. dist., with a down and partially decayed fir alongside, 40 ins. diam., with axe marks visible on burned blaze.  A fir, 43 ins. diam., bears S. 39° W., 26 lks. dist., with healed blaze.