

# County Surveyor's Record, Douglas County, Oregon

15435

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 19 S., R. 9 W., Willamette Meridian, Oregon

CHAINS	
	<p>A fir, 28 ins. diam., bears N. 26 1/2° E., 55 lks. dist., mkd. 1/4 S19 BT.</p> <p>An alder, 11 ins. diam., bears S. 37 1/2° E., 13 lks. dist., mkd. 1/4 S19 BT.</p> <p>Land, mountainous. Soil, rocky clay. Timber, fir, cedar, hemlock, maple, alder, chinquapin, madrone, and yew; undergrowth, vine maple, rhododendron, hazel, huckleberry, salmonberry, and fern.</p>
	<p>from the cor. of secs. 23, 24, 25, and 26.</p> <p>N. 0° 17' E., bet. secs. 23 and 24.</p> <p>Descend 90 ft. over NE. slope, through heavy timber and dense undergrowth.</p>
2.00	Ravine, drains N. 60° E.; asc. 15 ft. over SE. slope.
5.25	Spur, slopes NE.; desc. 340 ft. over N. slope.
11.50	Creek, 1 lk. wide, course S. 70° E.; asc. 90 ft. over SE. slope.
13.35	Spur, slopes E.; desc. 80 ft. over NE. slope.
17.30	Ravine, drains S. 50° E.; asc. 400 ft. over SE. slope.
35.20	Ravine, drains S. 20° E.; asc. 305 ft. over SW. slope, changing to S. slope.
40.64	<p>Point for the 1/4 sec. cor. of secs. 23 and 24, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 21 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <p>T 19 S R 9 W</p> <p>1/4</p> <p>S 23   S 24</p> <p>1968</p> </div> <p>from which</p> <p>A hemlock, 13 ins. diam., bears N. 31 1/2° E., 57 lks. dist., mkd. 1/4 S23 BT.</p> <p>A hemlock, 11 ins. diam., bears N. 16° W., 43 lks. dist., mkd. 1/4 S24 BT.</p> <p>Ascend 15 ft. over S. slope.</p>
41.30	Spur ridge, bears N. 65° W. and S. 65° E.; desc. 290 ft. over N. slope.
47.05	Creek, 3 lks. wide, course S. 80° E.; asc. 1,035 ft. over SE. slope.
81.28	The cor. of secs. 13, 14, 23, and 24, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.