

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, **15438**

T. 19 S., R. 9 W., Willamette Meridian, Oregon

CHAINS
78.00

Creek, 2 lks. wide, course S. 40° E.; asc. 280 ft. over S. slope.

80.50

Spur, slopes SE.; desc. 125 ft. over NE. slope.

82.40

Point for the cor. of secs. 22, 23, 26, and 27, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 19 S R 9 W
 $\frac{S 22 | S 23}{S 27 | S 26}$
 1968

from which

An alder, 18 ins. diam., bears N. 65° E., 13 lks. dist., mkd. T19S R9W S23 BT.

A hemlock, 13 ins. diam., bears S. 67° E., 17 lks. dist., mkd. T19S R9W S26 BT.

A fir, 15 ins. diam., bears S. 82° W., 69 lks. dist., mkd. T19S R9W S27 BT.

A cedar, 12 ins. diam., bears N. 68° W., 29 lks. dist., mkd. T19S R9W S22 BT.

Land mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, maple, chinquapin, alder, dogwood, and yew; undergrowth, vine maple, salmonberry, hazel, huckleberry, rhododendron, salal, and fern.

From the cor. of secs. 23, 24, 25, and 26.

S. 87° 09' W., bet. secs. 23 and 26.

Ascend 135 ft. over NE. slope, through heavy timber and dense undergrowth.

3.90

Ridge, bears N. 50° W. and S. 50° E.; desc. 245 ft. over SW. slope.

6.70

Dirt road, 20 lks. wide, bears N. 30° W. and S. 30° E.

8.75

Paved road, 30 lks. wide, bears N. 50° W. and S. 50° E.

13.00

Bottom of descent, slopes S.; asc. 135 ft. over SE. slope.

17.85

Spur, slopes S. 40° W.; desc. 465 ft. over NW. slope.

40.70

Point for the 1/4 sec. cor. of secs. 23 and 26, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 21 ins. in the ground, with brass cap mkd.

T 19 S R 9 W
 $\frac{1/4 \quad S 23}{S 26}$
 1968