

County Surveyor's Record, Douglas County, Oregon

15445

Dependent Resurvey, Portion of Subdivisional Lines,
T. 19 S., R. 9 W., Willamette Meridian, Oregon

CHAINS
81.16

The cor. of secs. 21, 22, 27, and 28.

Land, mountainous.
Soil, rocky clay.
Timber, fir, hemlock, cedar, maple, chinquapin, alder,
yew, madrone, and dogwood; undergrowth, salal, vine
maple, huckleberry, salmonberry, devil's club, hazel,
rhododendron, and fern.

N. 1° 53' E., bet. secs. 21 and 22.

Ascend 115 ft. over SW. slope, through heavy timber and
dense undergrowth.

5.20 Enter logged area, edge bears E. and W.

9.80 Creek, 2 lks. wide, course S. 10° E.; asc. 385 ft. over
broken S. slope.

33.10 Enter timber, edges bear E. and S. 20° W.

39.00 Top of ascent, slopes W.; desc. 20 ft. over NW. slope.

40.99 Point for the 1/4 sec. cor. of secs. 21 and 22, at propor-
tionate distance; there is no remaining evidence of the
original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 21 ins.
in the ground, with brass cap mkd.

T 19 S R 9 W
1/4
S 21 | S 22
1968

from which

A fir, 18 ins. diam., bears N. 79° E., 37 lks.
dist., mkd. 1/4 S22 BT.

A fir, 23 ins. diam., bears N. 18° W., 61 lks.
dist., mkd. 1/4 S21 BT.

Descend 20 ft. over NW. slope.

42.00 Creek, 1 lk. wide, course S. 10° W.; asc. 30 ft. over
SE. slope.

43.10 Spur, slopes E.; desc. 30 ft. over NE. slope.

44.30 Creek, 1 lk. wide, course S. 10° E.; asc. 360 ft. over
broken S. slope.

64.20 Dirt road, 25 lks. wide, bears NE. and SE. in curve.

66.10 Dirt road, 25 lks. wide, bears N. 20° W. and S. 20° E.

80.70 Ridge, bears E. and W.; desc. 85 ft. over N. slope.

81.98 Point for the cor. of secs. 15, 16, 21, and 22, at pro-
portionate distance; there is no remaining evidence of
the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 21 ins.
in the ground, with brass cap mkd.