

County Surveyor's Record, Douglas County, Oregon

15457

Dependent Resurvey, Portion of Subdivisional Lines,
T. 19 S., R. 9 W., Willamette Meridian, Oregon

CHAINS	
	<p>This control line was fully retraced and careful search was made for evidence of interveining corners, none of which was recovered.</p> <p>Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, maple, cedar, and chinquapin; undergrowth, vine maple, huckleberry, salmonberry, hazel, rhododendron, arrowwood, thimbleberry, Oregon grape, salal, and fern.</p>
	<p>From the cor. of secs. 15, 16, 21, and 22.</p> <p>West, bet. secs. 16 and 21.</p> <p>Descend 25 ft. over NW. slope, through heavy timber and dense undergrowth.</p>
2.50	Bottom of descent, slopes N.; 145 ft. over NE. slope.
18.20	Top of ascent, slopes N.; desc. 145 ft. over NW. slope.
27.70	Bottom of descent, slopes N.; asc. 70 ft. over NE. slope.
35.00	Ridge, bears N. 80° W. and S. 80° E.; asc. 20 ft. along S. slope.
40.00	<p>Point for the 1/4 sec. cor. of secs. 16 and 21; at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <p>1/4 <u>S 16</u> <u>S 21</u> T 19 S R 9 W 1969</p> </div> <p>from which</p> <p style="padding-left: 40px;">A fir, 15 ins. diam., bears N. 45° E., 38 lks. dist., mkd. 1/4 S16 BT.</p> <p style="padding-left: 40px;">A fir, 15 ins. diam., bears S. 4° E., 19 lks. dist., mkd. 1/4 S21 BT.</p> <p>Descend 90 ft. along S. slope.</p>
49.80	Ravine, drains S.; asc. 25 ft. over SE. slope.
52.00	Spur, slopes S.; desc. 145 ft. over SW. slope.
56.10	Ravine, drains S.; asc. 125 ft. over SE. slope.
60.70	Spur, slopes S. 30° E.; desc. 20 ft. over SW. slope.
65.20	Ravine, drains S. 30° E.; asc. 105 ft. over SE. slope.
70.50	Spur, slopes S.; desc. 55 ft. over SW. slope.
73.30	Ravine, drains S.; asc. 110 ft. over SE. slope.
80.00	The cor. of secs. 16, 17, 20, and 21.