

15542

Dependent Resurvey, Portion of Subdivisional Lines,
T. 30 S., R. 5 W., Willamette Meridian, Oregon

CHAINS	
11.70	Ridge, bears N., NE., and SW.; desc. 70 ft. over broken N. slope, along ridge top.
19.66	Point for the S 1/16 sec. cor. of secs. 9 and 10. Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd. S 1/16 F D O K P E R J O H N S T O N E S 9 S 10 1186 M103-1 1969 See BLM Re-monumentation on Pg 21463 from which A fir, 13 ins. diam., bears S. 14½° E., 53 lks. dist., mkd. S 1/16 S10 BT. A fir, 16 ins. diam., bears N. 56½° W., 29 lks. dist., mkd. S 1/16 S9 BT. Descend 105 ft. over broken N. slope.
26.20	Gravelled road, 20 lks. wide, bears NW. and SE.
31.00	Same gravelled road, 20 lks. wide, bears N. 20° E. and S. 20° W.
34.70	Ridge, bears NE. and S.; desc. 65 ft. over NW. slope.
36.40	Gravelled road, 20 lks. wide, bears N. 50° E. and S. 50° W.
39.32	The ¼ sec. cor. of secs. 9 and 10, monumented with the remains of the original corner tree, a fir snag, 18 ins. diam., with scribe mark S visible on opened blaze on W. face, from which the remains of the original bearing trees: A root hole, bears N. 63° W., 20 lks. dist., with a down fir alongside, 18 ins. diam., no marks visible. and new bearing trees A fir, 11 ins. diam., bears S. 34½° E., 87½ lks. dist., mkd. ¼ S10 BT. A cedar, 13 ins. diam., bears N. 85½° W., 196½ lks. dist., mkd. ¼ S9 BT. From this point, a local corner, established by James W. Byron, Deputy County Surveyor, in 1959, bears South, 0.02 chs. dist., monumented with an iron post, 1 in. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE F D O K P E R J O H N S T O N E ¼ S S 1186 M103-1 9 10 T 30 S R 5 W 1959 from which a bearing tree mkd. by Byron, in 1959 A fir, 8 ins. diam., bears N. 46° E., 67 lks. dist., with scribe marks ¼ S10 CS BT visible on partially healed blaze. and a bearing tree mkd. by Byron, in 1963