

Dependent Resurvey, Portion of Subdivisional Lines, **15554**  
T. 30 S., R. 5 W., Willamette Meridian, Oregon

## CHAINS

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.

T 30 S R 5 W  
S 18 | S 17  
S 19 | S 20  
1969

from which

A fir, 26 ins. diam., bears N.  $52^\circ$  E.,  $184\frac{1}{2}$  lks. dist., mkd. T30S R5W S17 BT.

A fir, 15 ins. diam., bears S.  $39^\circ$  E., 17 lks. dist., mkd. T30S R5W S20 BT.

A black oak, 7 ins. diam., bears S.  $74^\circ$  W., 17 lks. dist., mkd. T30S R5W S19 BT.

A black oak, 8 ins. diam., bears N.  $26\frac{1}{2}^\circ$  W., 59 lks. dist., mkd. T30S R5W S18 BT.

From this point, a local corner established by G. G. Stewart, County Surveyor, in 1922, and subsequently perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1961, bears S.  $43^\circ 44'$  E., 4.30 chs. dist., monumented with an iron post, 1 in. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE T30S R5W S17 S18 S19 S20 1961, from which the remains of bearing trees mkd. by Stewart:

A fir stump, 21 ins. diam., bears N.  $12\frac{1}{4}^\circ$  E.,  $52\frac{1}{2}$  lks. dist., with scribe marks S17 BT CS visible on opened blaze.

A fir stump, 24 ins. diam., bears S.  $28^\circ$  E., 56 lks. dist., with scribe marks 20 BT CS visible on opened blaze.

A fir stump, 22 ins. diam., bears S.  $53^\circ$  W.,  $33\frac{1}{2}$  lks. dist., with scribe marks 19 BT CS visible on opened blaze.

A fir stump, 18 ins. diam., bears N.  $26\frac{3}{4}^\circ$  W., 33 lks. dist., with scribe marks S18 visible on opened blaze.

and bearing trees mkd. by Byron

A fir, 18 ins. diam., bears N.  $\frac{1}{2}^\circ$  E.,  $99\frac{1}{2}$  lks. dist., with healed double blaze.

A fir, 16 ins. diam., bears S.  $73\frac{1}{2}^\circ$  E., 41 lks. dist., with scribe marks S20 CS BT visible on partially healed double blaze.

A twin madrone, 40 ins. diam., bears S.  $11\frac{1}{2}^\circ$  W., 133 lks. dist., with scribe marks T30S R5W S19 CS BT visible on partially healed double blaze.

A fir, 15 ins. diam., bears N.  $15^\circ$  W.,  $72\frac{1}{2}$  lks. dist., with healed blaze.

The Stewart corner was reported and recorded as being erroneously positioned by H. L. Eppstein, Deputy County Surveyor, in 1926.