

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS	
	Timber, fir, hemlock, cedar, maple, oak, myrtle, alder, and chinquapin; undergrowth, salal, poison oak, Oregon grape, vine maple, rhododendron, and fern.
	N. 0° 06' W., bet. secs. 20 and 21.
	Descend 40 ft. over NE. slope, through scattering timber and dense undergrowth.
2.75	Bottom of descent, slopes E.; asc. 35 ft. over SE. slope.
5.10	Top of ascent, slopes E.; desc. 30 ft. over NE. slope.
8.35	Bottom of descent, slopes E.; asc. 180 ft. over SE. slope.
15.30	Top of ascent, slopes E.; desc. 110 ft. over NE. slope.
19.35	Rock bluff, faces E.; desc. 55 ft. over NE. slope.
40.78	Point for the $\frac{1}{4}$ sec. cor. of secs. 20 and 21, at proportionate distance; there is no remaining evidence of the original corner.
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	$\frac{1}{4}$ S 20   S 21 T 28 S R 8 W 1975
	from which
	A fir, 4 ins. diam., bears N. 86° E., $14\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S21 BT.
	A fir, 6 ins. diam., bears S. 89 $\frac{1}{2}$ ° W., 26 lks. dist., mkd. $\frac{1}{4}$ S20 BT.
	Corner is located in bottom of descent, slopes E.
	Ascend 15 ft. over S. slope.
41.75	Top of ascent, slopes E.; desc. 60 ft. over NE. slope.
48.60	Ravine, drains S. 65° E.; asc. 25 ft. over SE. slope.
51.90	Spur, slopes N. 70° E.; desc. 20 ft. over NE. slope.
59.70	Bottom of descent, slopes E.; asc. 60 ft. over SE. slope.
69.30	Spur, slopes E.; desc. 25 ft. over NE. slope.
70.65	Ravine, drains S. 75° E.; asc. 30 ft. over SE. slope.
80.15	Spur, slopes S. 75° E.; desc. 10 ft. over NE. slope.
81.56	The cor. of secs. 16, 17, 20, and 21, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1957, monumented with an iron post, $1\frac{1}{2}$ ins. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.