

15586

Dependent Resurvey, Portion of Subdivisional Lines,
T. 28 S., R. 8 W., Willamette Meridian, Oregon

CHAINS	Timber, fir, hemlock, cedar, maple, oak, and chinquapin; undergrowth, salal, poison oak, rhododendron, Oregon grape, vine maple, and fern.
	N. 0° 03' W., bet. secs. 8 and 9.
	Ascend 70 ft. over S. slope, through scattering timber and dense undergrowth.
2.40	Spur, slopes S. 40° E.; desc. 45 ft. over NE. slope.
6.80	Ravine, drains N. 80° E.; asc. 5 ft. over SE. slope.
10.45	Spur, slopes E.; desc. 30 ft. over NE. slope.
14.80	Creek, 6 lks. wide, course S. 45° E.; asc. 125 ft. over SW. slope.
25.40	Spur, slopes N. 70° W.; desc. 5 ft. over NW. slope.
27.50	Ravine, drains W.; asc. 115 ft. over broken SW. slope.
35.45	Spur, slopes S. 55° W.; desc. 5 ft. over NW. slope.
36.50	Ravine, drains S. 65° W.; asc. 45 ft. over SW. slope.
39.64	Point for the $\frac{1}{4}$ sec. cor. of secs. 8 and 9, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. $\frac{1}{4}$ S 8 S 9 T 28 S R 8 W 1975 from which A fir, 6 ins. diam., bears N. $86\frac{1}{2}^\circ$ E., 13 lks. dist., mkd. $\frac{1}{4}$ S9 BT. A fir, 6 ins. diam., bears N. 39° W., 40 lks. dist., mkd. $\frac{1}{4}$ S8 BT. From this point, a local corner, established by Marvin Ramsey, RLS No. 404, in 1962, bears N. $59^\circ 20'$ E., 0.482 chs. dist., monumented with an iron pipe, $1\frac{1}{2}$ ins. diam., firmly set, projecting 2 ins. above ground, from which bearing trees mkd. by Ramsey: A fir, 14 ins. diam., bears S. 84° E., 19 lks. dist., with healed blaze. A fir, 11 ins. diam., bears S. $9\frac{1}{2}^\circ$ W., 16 lks. dist., with healed blaze. Ascend 10 ft. over SW. slope.
43.05	Ridge, bears N. 60° W. and S. 55° E.; desc. 340 ft. over NE. slope.
57.50	Leave timber, enter clear cut, edge bears E. and W.